Report for Embassy Golflinks - Cinnabar Hills

Date:10/10/2025

Quality Report

| Parameter | Avg Value | Min Limit | Max Limit | Exceedence |
|----------------|-----------|-----------|-----------|------------|
| ph | 7.45 | 7 | 7.46 | - |
| TURB | 0.01 | 0.01 | 0.01 | - |
| Temp | 28.52 | 27.32 | 29.26 | - |
| BOD | 5.79 | 3.87 | 9.56 | - |
| COD | 36.90 | 28.25 | 41.19 | - |
| TSS | 11.27 | 9.79 | 13.35 | - |
| cumulatingFlow | 0.00 | - | - | - |
| flowRate | 0.00 | - | - | - |
| energy | 0.00 | - | - | - |
| voltage | 0.00 | - | - | - |
| current | 0.00 | - | - | - |
| power | 0.00 | - | - | - |
| weight | 0.00 | - | - | - |

No energy report available.

Water Quality Report

| Station | Initial Reading | Final Reading | Consumption m3 |
|------------|-----------------|---------------|----------------|
| STP outlet | 124861.10 | 124950.20 | 89.10 |
| STP inlet | 129174.00 | 129326.60 | 152.60 |