Report for Embassy Golflinks - Hilton

Date:24/06/2025

Quality Report

| Parameter | Avg Value | Min Limit | Max Limit | Exceedence |
|----------------|-----------|-----------|-----------|------------|
| ph | 9.02 | 5.13 | 9.66 | - |
| TURB | 1.01 | 1.01 | 1.01 | - |
| Temp | 29.61 | 29.5 | 29.66 | - |
| BOD | 21.86 | 20.49 | 26.76 | - |
| COD | 45.78 | 43.68 | 53.32 | - |
| TSS | 19.92 | 19.13 | 22.74 | - |
| cumulatingFlow | 0.00 | - | - | - |
| flowRate | 0.00 | - | - | - |
| energy | 0.00 | - | - | - |
| voltage | 0.00 | - | - | - |
| current | 0.00 | - | - | - |
| power | 0.00 | - | - | - |
| weight | 0.00 | <u>-</u> | - | - |

No energy report available.

Water Quality Report

| Station | Initial Reading | Final Reading | Consumption m3 |
|------------|-----------------|---------------|----------------|
| STP outlet | 0.00 | 0.00 | 0.00 |
| STP inlet | 44471.70 | 44563.60 | 91.90 |