Report for Embassy Golflinks - Cinnabar Hills

Date:23/06/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	11.95	6.92	12.9	-
TURB	5.01	5.01	5.01	-
Temp	26.88	26.74	26.92	-
BOD	6.59	5.51	12.97	-
COD	23.60	21.93	33.41	-
TSS	18.23	17.6	21.9	-
cumulatingFlow	0.00	_	-	-
flowRate	0.00	_	-	-
energy	0.00	_	-	-
voltage	0.00	_	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	114280.60	114360.40	79.80
STP inlet	118567.90	118698.50	130.60