Report for Embassy Golflinks - Cinnabar Hills

Date:09/08/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.63	6	7.99	-
TURB	1.01	1.01	1.01	-
Temp	27.07	27.03	27.14	-
BOD	5.00	5	5	-
COD	25.00	25	25	-
TSS	4.00	4	4	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	117656.60	117721.90	65.30
STP inlet	123844.50	123936.90	92.40