Report for Embassy Golflinks - Pine Valley

Date:16/07/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.68	7.17	7.99	-
TURB	1.11	1.01	2	-
Temp	27.32	26.7	27.84	-
BOD	7.84	5	8	-
COD	29.75	25	30	-
TSS	8.73	4	10	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	0.00	0.00	0.00
STP inlet	118727.50	118954.60	227.10