Report for Embassy Golflinks - Torrey Pines

Date:23/09/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.42	7	7.46	-
TURB	0.01	0.01	0.01	-
Temp	28.20	27.32	29.26	-
BOD	7.23	3.87	9.56	-
COD	35.98	28.25	38.07	-
TSS	12.03	9.79	15.11	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	316038.30	316038.30	0.00
STP inlet	121721.70	121721.70	0.00