## **Report for Embassy Golflinks - Hilton**

Date:09/08/2025

## **Quality Report**

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	0.00	0	0	-
TURB	1.01	1.01	1.01	-
Temp	29.00	29	29	-
BOD	8.00	8	8	-
COD	30.00	30	30	-
TSS	10.00	10	10	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

## **Water Quality Report**

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	4946.23	4946.23	0.00
STP inlet	42798.30	42884.20	85.90