Report for Embassy Golflinks - Hilton

Date:23/06/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	9.19	5.13	9.72	-
TURB	1.01	1.01	1.01	-
Temp	29.60	29.5	29.68	-
BOD	21.35	19.09	23.96	-
COD	45.01	41.53	49.01	-
TSS	19.62	18.32	21.13	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	0.00	0.00	0.00
STP inlet	44363.00	44452.60	89.60