Report for Embassy Golflinks - MLCP

Date:09/08/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.79	7.4	7.95	-
TURB	1.01	1.01	1.01	-
Temp	29.05	28.98	29.11	-
BOD	5.00	5	5	-
COD	25.00	25	25	-
TSS	4.00	4	4	-
cumulatingFlow	0.00	_	-	-
flowRate	0.00	_	-	-
energy	0.00	_	-	-
voltage	0.00	_	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	187758.70	188140.59	381.89
STP inlet	121904.60	122281.70	377.10