Report for Embassy Golflinks - Cinnabar Hills

Date:20/06/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	8.26	7.29	9.65	-
TURB	5.01	5.01	5.01	-
Temp	26.90	26.76	26.94	-
BOD	7.27	6.11	12.85	-
COD	24.65	22.85	33.23	-
TSS	18.62	17.95	21.84	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	114085.10	114167.50	82.40
STP inlet	118347.50	118457.40	109.90