Report for Embassy Golflinks - Hilton

Date:20/06/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	8.75	4.84	9.02	-
TURB	1.01	1	1.01	-
Temp	29.62	29.5	29.7	-
BOD	17.01	11.62	68.28	-
COD	38.33	30.04	117.19	-
TSS	17.13	14.01	46.7	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	0.00	0.00	0.00
STP inlet	44026.90	44134.10	107.20