Report for Embassy Golflinks - Torrey Pines

Date:28/06/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	5.57	7	12.89999962	-
TURB	0.82	1.00999999	1.00999999	-
Temp	23.23	28.68000031	28.75	-
BOD	4.04	5	5	-
COD	20.21	25	25	-
TSS	5.66	7	7	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	280089.00	280273.19	184.19
STP inlet	188856.30	189139.91	283.61