

Report for Embassy Golflinks - Hilton

Date:25/01/2026

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.48	7.21	7.5	-
TURB	1.01	1.01	1.01	-
Temp	27.44	27.23	27.81	-
BOD	9.35	9.24	9.39	-
COD	45.38	44.97	45.52	-
TSS	9.22	9.11	9.26	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

No water quality report available.