Report for Embassy Golflinks - MLCP

Date:20/06/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.94	7.76	8.09	-
TURB	0.00	0	0	-
Temp	0.00	0	0	-
BOD	0.00	0	0	-
COD	0.00	0	0	-
TSS	0.00	0	0	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	179881.70	179891.70	10.00
STP inlet	113221.10	113239.40	18.30