Report for Embassy Golflinks - MLCP

Date:10/10/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.42	7	7.46	-
TURB	0.01	0.01	0.01	-
Temp	28.35	27.32	29.26	-
BOD	6.44	3.87	9.56	-
COD	37.32	28.25	42.85	-
TSS	11.58	9.79	15.11	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	197366.90	197545.70	178.80
STP inlet	135054.40	135264.80	210.40