Report for Embassy Golflinks - Pine Valley

Date:25/07/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	6.00	6	6	-
TURB	0.88	1.01	1.01	-
Temp	21.10	27.39	27.51	-
BOD	7.76	8	8	-
COD	24.25	30	30	-
TSS	8.22	8.39	8.68	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	15897.60	15979.00	81.40
STP inlet	120160.60	120326.00	165.40