Report for Embassy Golflinks - Cinnabar Hills

Date:23/09/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.40	7	7.46	-
TURB	0.01	0.01	0.01	-
Temp	28.72	27.32	29.26	-
BOD	6.99	3.87	9.56	-
COD	36.13	28.25	39.14	-
TSS	11.40	9.79	13.53	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	119532.10	119532.10	0.00
STP inlet	127526.40	127658.30	131.90