Report for Embassy Golflinks - Pine Valley

Date:23/06/2025

Quality Report

| Parameter | Avg Value | Min Limit | Max Limit | Exceedence |
|----------------|-----------|-----------|-----------|------------|
| ph | 7.68 | 7.43 | 8 | - |
| TURB | 7.01 | 4.01 | 4004 | - |
| Temp | 28.09 | 27.82 | 28.16 | - |
| BOD | 10.56 | 6.43 | 61.28 | - |
| COD | 29.71 | 23.35 | 107.73 | - |
| TSS | 20.52 | 18.13 | 49.78 | - |
| cumulatingFlow | 0.00 | - | - | - |
| flowRate | 0.00 | - | - | - |
| energy | 0.00 | - | - | - |
| voltage | 0.00 | - | - | - |
| current | 0.00 | - | - | - |
| power | 0.00 | - | - | - |
| weight | 0.00 | <u>-</u> | - | - |

No energy report available.

Water Quality Report

| Station | Initial Reading | Final Reading | Consumption m3 |
|------------|-----------------|---------------|----------------|
| STP outlet | 17333.70 | 17490.40 | 156.70 |
| STP inlet | 122091.60 | 122229.40 | 137.80 |