Report for Embassy Golflinks - Torrey Pines

Date:20/06/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.51	7.150000095	8	-
TURB	1.01	1.00999999	1.00999999	-
Temp	28.43	28.25	28.52000046	-
BOD	5.18	5	23.25	-
COD	25.19	25	49.68999863	-
TSS	7.11	7	17.76000023	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	280897.31	281604.50	707.19
STP inlet	183401.50	183957.50	556.00