Report for Embassy Golflinks - MLCP

Date:24/06/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.86	7.53	7.98	-
TURB	5.01	5.01	5.01	-
Temp	28.91	28.77	28.98	-
BOD	6.41	4.34	10.67	-
COD	16.92	13.98	23.72	-
TSS	23.31	22.12	25.77	-
cumulatingFlow	0.00	_	-	-
flowRate	0.00	-	-	-
energy	0.00	_	-	-
voltage	0.00	_	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	180495.20	180591.30	96.10
STP inlet	113933.90	114040.00	106.10