Report for Embassy Golflinks - Torrey Pines

Date:10/10/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.41	7	7.46	-
TURB	0.01	0.01	0.01	-
Temp	28.39	27.32	29.26	-
BOD	5.75	3.87	9.56	-
COD	37.32	28.25	42.46	-
TSS	11.07	9.79	12.88	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	324340.50	325089.90	749.40
STP inlet	11150.70	11341.50	190.80