Report for Embassy Golflinks - Hilton

Date:28/06/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.91	6	7.99	-
TURB	1.02	1.01	2	-
Temp	29.62	29.52	29.68	-
BOD	5.42	5	8	-
COD	25.51	25	30	-
TSS	4.19	4	10	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	0.00	0.00	0.00
STP inlet	44960.20	44996.10	35.90