Report for Embassy Golflinks - Hilton

Date:25/07/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
parameters	NaN	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	3647.65	3647.65	0.00
STP inlet	40960.40	40960.40	0.00