Report for Embassy Golflinks - Torrey Pines

Date:24/06/2025

Quality Report

| Parameter | Avg Value | Min Limit | Max Limit | Exceedence |
|----------------|-----------|-------------|-------------|------------|
| ph | 7.73 | 7.340000153 | 8.359999657 | - |
| TURB | 198.26 | 1.00999999 | 4001 | - |
| Temp | 28.35 | 26.13999939 | 28.52000046 | - |
| BOD | 6.71 | 5 | 201.5299988 | - |
| COD | 27.57 | 25 | 323.9700012 | - |
| TSS | 7.99 | 7 | 120.6200027 | - |
| cumulatingFlow | 0.00 | - | - | - |
| flowRate | 0.00 | - | - | - |
| energy | 0.00 | - | - | - |
| voltage | 0.00 | - | - | - |
| current | 0.00 | - | - | - |
| power | 0.00 | - | - | - |
| weight | 0.00 | - | - | - |

No energy report available.

Water Quality Report

| Station | Initial Reading | Final Reading | Consumption m3 |
|------------|-----------------|---------------|----------------|
| STP outlet | 276670.19 | 277671.50 | 1001.31 |
| STP inlet | 185526.20 | 186237.00 | 710.80 |