Report for Embassy Golflinks-Sunriver

Date:16/07/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.80	7.62	7.96	-
TURB	1.01	1.01	1.01	-
Temp	26.88	26.63	27.19	-
BOD	8.00	8	8	-
COD	28.73	26.86	30	-
TSS	10.00	10	10	-
cumulatingFlow	0.00	_	-	-
flowRate	0.00	_	-	-
energy	0.00	_	-	-
voltage	0.00	_	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	56753.00	56815.90	62.90
STP inlet	58036.50	58110.30	73.80