Report for Hilton Manyata

Quality Report for Station: STP

Parameter	Avg Value	Min Value	Max Value	Min Acceptable Limits	Max Acceptable Limits	Exceedance
ph	6.74	0	0	Not Added	Not Added	Not Added
turbidity	40.89	0	0	Not Added	Not Added	Not Added
Temp	126.34	0	0	Not Added	Not Added	Not Added
BOD	21.77	0	0	Not Added	Not Added	Not Added
COD	32.32	0	0	Not Added	Not Added	Not Added

Quality Report for Station: STP-energy

Parameter	Avg Value	Min Value	Max Value	Min Acceptable Limits	Max Acceptable Limits	Exceedance
energy	1	0	0	Not Added	Not Added	Not Added

Quality Report for Station: ETP outlet

Parameter	Avg Value	Min Value	Max Value	Min Acceptable Limits	Max Acceptable Limits	Exceedance
cumulatingFlow	0.3	0	0	Not Added	Not Added	Not Added

Quality Report for Station: STP inlet

	Parameter	Avg Value	Min Value	Max Value	Min Acceptable Limits	Max Acceptable Limits	Exceedance
cu	mulatingFlow	50	0	0	Not Added	Not Added	Not Added

Quality Report for Station: STP softener outlet

Parameter	Avg Value	Min Value	Max Value	Min Acceptable Limits	Max Acceptable Limits	Exceedance
cumulatingFlow	2.22	0	0	Not Added	Not Added	Not Added

Quality Report for Station: STP acf outlet

Parameter	Avg Value	Min Value	Max Value	Min Acceptable Limits	Max Acceptable Limits	Exceedance	
cumulatingFlow	0	0	0	Not Added	Not Added	Not Added	

Quality Report for Station: STP garden outlet 1

Parameter	Avg Value	Min Value	Max Value	Min Acceptable Limits	Max Acceptable Limits	Exceedance
cumulatingFlow	38.7	0	0	Not Added	Not Added	Not Added

Quality Report for Station: STP uf outlet

Parameter	Avg Value	Min Value	Max Value	Min Acceptable Limits	Max Acceptable Limits	Exceedance
cumulatingFlow	1.58	0	0	Not Added	Not Added	Not Added