

# Report for Embassy Golflinks - MLCP

Date:25/01/2026

## Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.41	7	7.46	-
TURB	0.01	0.01	0.01	-
Temp	28.26	27.32	29.26	-
BOD	7.06	3.87	9.56	-
COD	38.12	28.25	41.68	-
TSS	11.69	9.79	17.7	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

No water quality report available.