Report for Hilton Manyata

Quality Report for Station: STP

Parameter	Avg Value	Min Value	Max Value	Min Acceptable Limits	Max Acceptable Limits
ph	6.74	0	0	Not Added	Not Added
turbidity	40.89	0	0	Not Added	Not Added
Temp	126.34	0	0	Not Added	Not Added
BOD	21.77	0	0	Not Added	Not Added
COD	32.32	0	0	Not Added	Not Added

Energy Report

Station	Initial Reading	Final Reading	Difference
STP	789.9	789.9	nil

Flow Report

Station	Initial Reading	Final Reading	Difference
ETP outlet	641.9000244	702	60.09997559999999
STP inlet	nil	nil	nil
STP UF outlet	nil	nil	nil
STP softener outlet	nil	nil	nil
STP outlet	nil	nil	nil