Report for Embassy Golflinks - Cinnabar Hills

Date:16/07/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.66	6	7.99	-
TURB	1.01	1.01	1.01	-
Temp	26.96	26.87	27.05	-
BOD	5.01	5	6.51	-
COD	25.00	25	25	-
TSS	5.15	4.46	7.03	-
cumulatingFlow	0.00	_	-	-
flowRate	0.00	_	-	-
energy	0.00	_	-	-
voltage	0.00	_	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	115535.70	115622.90	87.20
STP inlet	120939.30	121098.40	159.10