## **Report for Embassy Golflinks - Hilton**

Date:23/09/2025

## **Quality Report**

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.49	7.45	7.5	-
TURB	1.01	1.01	1.01	-
Temp	30.16	29.76	30.23	-
BOD	9.35	9.24	9.39	-
COD	45.39	44.97	45.52	-
TSS	9.22	9.11	9.26	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

## **Water Quality Report**

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	9073.17	9213.21	140.04
STP inlet	53268.20	53371.70	103.50