

Report for Embassy Golflinks - Pine Valley

Date:25/01/2026

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.41	7	7.46	-
TURB	0.01	0.01	0.01	-
Temp	28.05	27.32	29.26	-
BOD	5.91	3.87	8.84	-
COD	36.92	28.25	39.92	-
TSS	11.75	9.79	14.83	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

No water quality report available.