## **Report for Embassy Golflinks - Hilton**

Date:16/07/2025

## **Quality Report**

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	6.97	7	7	-
TURB	1.01	1.01	1.01	-
Temp	29.00	29	29	-
BOD	8.00	8	8	-
COD	30.00	30	30	-
TSS	10.00	10	10	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

## **Water Quality Report**

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	2833.24	2933.54	100.30
STP inlet	40216.90	40352.20	135.30