Report for Embassy Golflinks - MLCP

Date:25/07/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	7.30	6.77	7.44	-
TURB	1.01	1.01	1.01	-
Temp	28.39	28.34	28.46	-
BOD	5.00	5	5	-
COD	25.00	25	25	-
TSS	4.00	4	4	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	178892.70	179040.30	147.60
STP inlet	112847.80	112996.10	148.30