


ITAE of lateral error by active controller



Baseline-NN-MSE-decay-mu failed in lap 2