Handleiding - Engels

Manual - Correct execution of a rinse

1. Preparation

1.1. Disconnecting the hose: At the end of filling, disconnect the hose from the tank and connect it to the rinse water tank.

1.2. Blowing out the machine:

- Start the blow-out cycle via SCADA.

- Check if the pipe is completely empty.

- If not, start the blow-out cycle again.

2. Cleaning the filter

2.1. Remove the filter from the filter housing and clean it with water.

2.2. Place the filter back and tighten the screws securely.

3. Removing residual product

3.1. Open the steel tap and the valve to remove residual product from the machine.

3.2. Do not forget to close the valves after draining.

4. Starting the rinse cycle

4.1. On the SCADA interface, press 'rinse' and the cycle will start automatically.

5. Inspection & completion

5.1. Observe the water outflow during rinsing and check if it is clear.

5.2. In the future, a refractometer will automatically indicate when rinsing is complete.