

1. Approving Civil Aviation Authority/Country FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: R3834	
4. Organization Name and Address: Icon Aerospace, LLC 600 RADIATOR ROAD INDIAN TRAIL, NC 28079		5. Work Order/Contract/Invoice Number: W315655				6. Remarks: OVERHAULED in Accordance with PARKER-HANNIFIN CMM 36-10-12 Rev.:27 Date:18/Jan/2024	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:		
N/A	VALVE, 6" BLEED AIR MANIFOLD	2780539-107	1	3358	OVERHAULED		
FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER: W315655		COMPLIANCE WITH MANDATORY AIRWORTHINESS DIRECTIVES (ADs): N/A		COMPLIANCE WITH SERVICE BULLETINS (SBs/EOs): N/A			
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		14b. Authorized Signature: 		14c. Approval/Authorization No.: 68IR700B	
13b. Authorized Signature:		13c. Approval/Authorization No.:		14d. Name (Typed or Printed): MATTHEW S. JACKSON		14e. Date (dd/mm/yyyy): 11/Mar/2026	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):					
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

1. Approving Civil Aviation Authority/Country FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: R3834	
4. Organization Name and Address: Icon Aerospace, LLC 600 RADIATOR ROAD INDIAN TRAIL, NC 28079		FAA Repair Station : 68IR700B CAA Reference: UK.145.50014 Ph: 704.821.4266 Fax:				5. Work Order/Contract/Invoice Number: W315655	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:		
N/A	VALVE, 6" BLEED AIR MANIFOLD	2780539-107	1	3358	OVERHAULED		
12. Remarks: OVERHAULED in Accordance with PARKER-HANNIFIN CMM 36-10-12 Rev.:27 Date:18/Jan/2024							
FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER: W315655							
COMPLIANCE WITH MANDATORY AIRWORTHINESS DIRECTIVES (ADs): N/A							
COMPLIANCE WITH SERVICE BULLETINS (SBs/EOs): N/A							
This repair/modification/overhaul/inspection was performed with personnel who were part of a current drug and alcohol testing program as required by 14CFR120. Certifies that the work specified in block 11/12 was carried out in accordance with (UK) Part-145 and in respect to that work the component is considered ready for release to service under (UK) Part-145 Approval Number: UK 145.50014							
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		14b. Authorized Signature: 			14c. Approval/Authorization No.: 68IR700B
13b. Authorized Signature:		13c. Approval/Authorization No.:		14d. Name (Typed or Printed): MATTHEW S. JACKSON			
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 11/Mar/2026			
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							



FAA REPAIR STATION 68IR700B
EASA REFERENCE 145.6295
600 RADIATOR ROAD
INDIAN TRAIL, NC 28079
Ph: 704.821.4266 Fax:
Email: service@iconaerospace.com

Page 1

WORK ORDER

W315655

Date Released: 11/Mar/2026

TEARDOWN REPORT

VELO AVIATION	Cust RO#: R3834	Manuals		
4040 SORRENTO VALLEY BLVD SUITE G	P/N: 2780539-107	Loc	ATA	Revision
SAN DIEGO, CA 92121	S/N: 3358	PA-027	36-10-12	27 18/Jan/2024
Contact: GREGG HAMES	Desc: VALVE, 6" BLEED AIR			
Contact Ph: 619-356-2116	MANIFOLD			
Contact Fax: 619-353-3824	Mfgr: PARKER-HANNIFIN			

Work Requested UNIT RECEIVED FOR OVERHAUL AS PER O.E.M SPECS

FINDINGS

RECEIVING INSPECTION:
VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND.
PLEASE OVERHAUL

PRELIMINARY INSPECTION:
PASSED

HIDDEN DAMAGE:
NONE

CONTINUED INSPECTION:
TESTED UNIT. PASSED FUNCTIONAL TEST. DISASSEMBLY IS REQUIRED FOR CLEANING.

CORRECTIVE ACTION: UNIT CONDITION OVERHAULED
CLEANED AND REASSEMBLED UNIT. TESTED AS PER O.E.M. SPEC'S. ALL WORK PERFORMED AS PER O.E.M SPEC'S.

SB'S, AD'S AND RMK'S:
NONE

CERTIFICATION

SERVICE PERFORMED: ☒ OVERHAULED


PARTS AND MATERIALS

QTY	PART NUMBER	SERIAL NUMBER	DESCRIPTION	COND
-----	-------------	---------------	-------------	------

MAINTENANCE RELEASE

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY:


MATTHEW S. JACKSON

DATE: 11/Mar/2026