






CAUTION CAUTION
CONTAINS PARTS AND
ASSEMBLIES SUSCEPTIBLE TO DAMAGE BY
ELECTROSTATIC DISCHARGE (ESD)

AERO INSTRUMENTS, A JONCK, INC.
FUNCTIONALLY TESTED
WARRANTY VOID IF
REMAINED OPEN

AERO INSTRUMENTS
A JONCK, INC.



MFR 4V792



SER 178466

DMF 121982

MODS ☒ ☒ 3 4 5 6 7 8 9 10 11 12 13 14
15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
31 32 33 34 35 36 37 38 39 40 A B C D E F

FLIGHT CONTROL COMPUTER

TYPE NO. FCC-703

BOEING SCD S241T100-151

WT 18.2 LB

FAA-PMA

COLLINS PNR 822-1261-101



Rockwell Collins, Inc.
Cedar Rapids, Iowa 52498-0001 USA



FCC-703

CAUTION
UP TO 120 VOLTS INSIDE
EXPOSED TERMINALS
WITH COVER REMOVED

MPR 4V792

SER 176468

DMP 121962

MODE JCDC D 1 4 1 5 1 6 1 7 1 8 1 9 1 10 1 11 1 12 1 13 1 14
15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
31 32 33 34 35 36 37 38 39 40 A B C D E F

FLIGHT CONTROL COMPUTER

TYPE NO. FCC-703
BOEING SCD 5241T100-151

WT 18.2 LB
FAA-PMA

COLLINS PNR 822-1261-101

Rockwell Collins, Inc.
Cedar Rapids, Iowa 52498-0001 USA



Collins

J22



FCC-703


Loadable Software Airplane
Part (LSAP) ID Tag

CAUTION

THIS TAG IS TO BE REMOVED
UPON AIRPLANE INSTALLATION

This LRU has been pre-loaded with
Loadable Software Airplane Part(s). Shop
testing of this unit may result in LSAP(s)
being overwritten.

NOTE: All Loadable Software Airplane
Part(s) must be verified per the Aircraft
Maintenance Manual (AMM) after LRU
installation on the aircraft. Information
contained on this tag does not imply
Aircraft Configuration.



AERO INSTRUMENTS & AVIONICS, INC.
3332 WALDEN AVENUE, STE. 150
DEPEW, NY 14043 USA
FAA AIR AGENCY CERT NO. NC1R343K
EASA CERT NO. EASA.143.A037
UK CAA CERT NO. UK.145.59119
INSTRUMENT CLASS 1-2-3-4
RADIO CLASS 1-2-3
ACCESSORY CLASS 2-3
PHONE: 716-694-7060 FAX 716-694-7394
<http://www.aeroinst.com>

TS & AVIONICS, INC.
FUNCTIONALLY TESTED
WARRANTY VOID IF
SEAL IS BROKEN



06324 SLS

