Lab 3: Link State Routing and Layer 3 Redundancy

CNIT34500-006
Group 2
Laura Fung
Ethan Hammond
Submitted To: Dominic Russo
Date Submitted: 04/18/2023
Date Due: 04/18/2023

Table of Contents

Table of Co	ontents	ii
Executive S	Summary	4
Business So	cenario	5
Procedures	S	8
	Removed Unnecessary Configurations and adding required hardware	8
	Added Required Hardware	8
	Configured Loopback Interfaces	9
	Configured /30 Networks	. 10
	Configured VLANs on Routers	. 10
	Created VLANs on Switches	. 11
	Configured Layer 2 Switch	. 11
	Configured Layer 3 Switches	. 12
	Implemented OSPF	. 13
	Implemented EIGRP	. 14
	Configured Redistribution and license enabling	. 15
	Configured GLBP and NTP	. 16
	Configured NTP	. 16
	Configured ICMP Strings	. 17
	Configured SNMP monitoring on LibreNMS	. 18
	Configured 6504 as DHCP Server	. 19
	Configured Additional DHCP Servers	. 19
Conclusion	as and Dagamman dations	21

RESULTS	23
Biblography	25
APPENDIX A: Problem Solving	27
APPENDIX B: Tables	31
Table 1: 2811 Console Cabling	31
Table 3: Term Server Menu Mapping	32
Table 4: IOS Files	32
Table 5: Network Cabling Information	33
Table 6: Loopback Addressing Information	33
Table 7: Interface Addressing Information	34
Table 8a: OSPF network information	35
Table 8b: EIGRP network information	37
Table 9: PC IP Addressing Information	38
Table 10: DHCP Information	38
APPENDIX C: Router and Switch Configurations	40
2811 Term Server	40

EXECUTIVE SUMMARY

The main goals of this project were to configure the routers and switches with a link state protocol and other layer 3 redundancy protocols- such as Gateway Load Balancing Protocol (GLBP) and Open Shortest Path First (OSPF). Furthermore, network connectivity needed to be established between the varying routing protocols- OSPF and Enhanced Interior Gateway Protocol (EIGRP).

In the following report, the Business Case describes the lab and its requirements in further detail, including the logical and physical diagrams of the network as it was before the lab completion. The Procedures section lists all the steps taken to complete the objectives with details in the descriptions before each. The Results section includes the lab in its final form, with updated logical and physical diagrams showing changes made. The Conclusions and Recommendations section states whether the project met all the requirements and expectations of the Business Case, and includes any recommendations for further implementations. The appendices include tables, problem solving write ups, and each router/switch's configuration files.

BUSINESS SCENARIO

The company needed to modify their network to be able to use multiple routing protocols. They needed to start by changing their 4 Virtual Local Area Network (VLAN) IDs to VLANs 1002, 2002, and 3002- plus the native VLAN. To meet the network design requirements, multiple Enhanced High-speed WAN Interface Cards (EHWICs) needed to be ordered and placed into the network devices to allow for fiber channel connections, and to add additional Network Interface Cards (NICs) to routers to allow for more concurrent connections.

Three OSPF areas and two EIGRP autonomous systems (AS) were required to segment the network. OSPF areas 2 and 102 should be created, alongside area 0 to interconnect them. EIGRP autonomous systems 2 and 102 should also be created but should not be directly connected to area 0. As a result, redistribution would need to be implemented to pass network traffic between OSPF and EIGRP networks.

Dynamic Host Configuration Protocol (DHCP) should also be configured to automatically assign IP addresses and gateways to their hosts on their respective VLANs.

The 6504 should serve as the DHCP server for all three OSPF areas, and the 1921 and 3750-C should serve as DHCP servers for their EIGRP autonomous systems, for a total of 3 DHCP servers serving out 192.168.X.0/24 networks for their respective VLANs.

Network Time Protocol (NTP) should also be configured on all network devices to synchronize to CIT net and set the correct time zone. A Trivial File Transfer Protocol (TFTP) server should be set up and all network devices should be configured to automatically backup their configuration files to the server periodically. Additionally, LibreNMS should be used

for Simple Network Management Protocol (SNMP) monitoring for all network devices.

Physical and logical diagrams of the initial network were provided in figures 1 and 2 below.




Figure 1: Initial Physical Diagram




Figure 2: Initial Logical Diagram

PROCEDURES

The procedures section was broken up into major groups of steps. In the steps, the **buttons pressed** were bolded, *options* were italicized, text entered into console/terminal was typed in Courier New, menu navigation and repeated actions were shown with the | pipe | symbol. Repeated steps were shortened by referencing specific information in the Appendix. Varying input is also placed between [brackets].

Removed Unnecessary Configurations and adding required hardware

Before beginning, it was necessary to remove any conflicting configurations. Since this new network implemented completely different protocols and IP schemes, completely wiping each device's configuration was found to be easier than manually removing each one. This was done with the steps below.

- 1. Logged into the device and entered write erase to erase the startup config.
- 2. Used reload to restart the device.
- 3. Used write memory to save the blank config as the startup config.

Added Required Hardware

Before configuring devices, additional hardware was needed to meet the network design requirements. This included EHWIC cards- to add interfaces to routers and implement fiber channel, and Double Wide Service Modules (DWSMs). It was imperative to power the devices off before inserting the hardware.

- 4. Added an EHWIC card to the 2911b to allow for a fiber channel between itself and the 2901A.
- 5. Added two EHWIC cards to the 2901a to allow for a fiber channel to the 2911b and to the 6504.
- 6. Installed an EHWIC card on the 2911a to allow for a fiber channel to the 2901b.
- 7. Added an EHWIC card to the 2901b to allow for a fiber channel to the 2911A.
- 8. Installed a Double Wide Service Module to the 2901b to allow for end devices to be plugged in and act as a switchport.

Configured Loopback Interfaces

Loopback interfaces were configured on each router and switch to test network connectivity. Since these virtual interfaces were used primarily to ping one another, /32 networks were used to simplify addressing and avoid wasting addresses.

- 1. Logged into the 2911a.
- 2. Entered en
- 3. Entered conf t
- 4. Entered interface loopback 0
- 5. Entered ip address [169.254.1.96] [255.255.255.255]
 - a. Repeated steps 2-5 on all devices- see Appendix A for loopback addressing information.

Configured /30 Networks

Networks between routers can be condensed into the smallest possible subnet of a /30. Since this allows for 2 devices, it is perfectly sized for router interconnects. All router interconnect interfaces were configured with /30 networks.

- 1. Entered conf t
- 2. Used int [gig0/1] to enter the interface between the two routers.
- 3. Used IP address [192.168.254.9] [255.255.255.252] to set the IP address.
 - a. Repeated steps 1-3 on all devices- see Appendix A for IP addressing information.

Configured VLANs on Routers

One requirement for this network design was 4 separate VLANs. Since VLAN 1 serves as the default and is present when no other VLAN configurations are made, VLANs 1002, 2002, and 3002 were added to total 4 VLANs. VLANs were configured on routers by creating sub interfaces and assigning each one a /24 network.

- 4. Entered conf t
- 5. Entered int [gigabitEthernet 0/1.2002]
- 6. Entered encapsulation dot1q [2002]
- 7. Entered ip address [192.168.12.1] [255.255.255.0]
- 8. Entered no shut
 - a. Repeated steps 2-5 for each sub interface on all routers- see Appendix A for VLAN addressing information.

Created VLANs on Switches

Similarly, VLAN 1 is the default on switches when no VLAN configurations are made. Therefore, VLANs 1002, 2002, and 3002 were added by creating a virtual interface for each VLAN. A management IP was also assigned to each VLAN.

- 1. Entered conf t
- 2. Entered vlan [2002]
 - a. Repeated step 2 for VLANs 102, 2002, and 3002 on all switches
- 3. Used interface vlan [102, 2002, 3002] to enter the VLAN interfaces.
- 4. Typed ip address 192.168.12.10 255.255.255.0 to add a management IP for VLAN 102.
- 5. Typed ip address 192.168.22.10 255.255.255.0 to add a management IP for VLAN 2002.
- Typed ip address 192.168.32.10 255.255.255.0 to add a management IP for VLAN 3002.

Configured Layer 2 Switch

The 3750 switches operate on layer 2 by default. To provide connectivity to its connected interfaces, the ports simply have to be trunked to allow the respective VLAN traffic through. In this case, interfaces were trunked on the 3750-B to allow traffic from all four VLANs through.

- 1. Entered conf t
- 2. Entered the interfaces that are connected to the 2901A and the 2911A routers.
- 3. Used switchport trunk allowed vlan 1,102,2002,3002.

- 4. Entered switchport trunk encapsulation dot1q.
- 5. Used switchport mode trunk to trunk the VLANs.
- 6. Created the VLAN interfaces with int [vlan102] [vlan2002], [vlan3002].
- 7. Created the VLANs with vlan102, vlan2002, and vlan3002.
- 8. Assigned IP addresses to these interfaces with ip address [192.168.9.5] [255.255.255.0]
 - a. See Appendix A for IP addressing information.

Configured Layer 3 Switches

Since the 3750 switches operate on layer 2 by default, additional configurations must be made for them to use routing functions. This was done by converting each interface to routing mode, and assigning each an IP within a /30 network.

- 1. Entered conf t.
- 2. Used ip routing to enable IP routing capabilities on a L3 switch.
- Entered the interfaces that were interconnects between the switches and routers using the int command.
- 4. Used no switchport to turn it into an L3 link.
- 5. Assigned an IP address with ip address [192.168.254.22] [255.255.255.252].
- 6. Repeated steps 1-5 on the Cisco 3750A and 3750C.
 - a. See Appendix A for IP addressing information

Implemented OSPF

Open Shortest Path First (OSPF) was implemented as a primary routing protocol in the network as it is a reliable link-state routing protocol. OSPF is configured by creating a process ID and defining adjacent networks to each router in each specified OSPF area.

6504

- 1. Used conf t to enter configuration mode.
- 2. Typed router ospf 2 to enter ospf configuration.
- 3. Entered network [169.254.1.0] [0.0.0.255] area 0 to add network adjacencies.
 - a. Added all directly connected networks including the 2901A/30 link and the 2911A/30 link.
 - b. Added all area 0 VLAN networks with network 192.168.[7, 8, 9].0 [255.255.255.0] area 0.
- 4. Used default-information originate.

2901A

- 5. Typed router ospf 2 to enter ospf configuration.
- 6. Entered network [169.254.1.0] [255.255.255.0] area 0 for loopback addresses.
- 7. Entered network [192.168.254.4] [255.255.255.252] area 0 for the 6504 interconnect.
- 8. Used network [192.168.[7,8,9].0] [255.255.255.0] area 0 for the area 0 VLANs.

 Used network [192.168.[4,5,6].0] [255.255.255.0] area 102 for the area 102 VLANs.

2911B

- 10. Typed router ospf 2 to enter ospf configuration.
- 11. Entered network [169.254.1.0] [255.255.255.0] area 102 for IP address connections.
- 12. Repeated step 2 for all networks connected shown in Appendix A.

2911A

- 13. Typed router ospf 2 to enter ospf configuration
- 14. Entered network [169.254.1.0] [255.255.255.0] area 2 for all IP addresses in Area 2.
- 15. Entered network [192.168.[7,8,9].0] [255.255.255.0] area 0 for all area 0 IP addresses.

2901B

- 16. Typed router ospf 2 to enter ospf configuration.
- 17. Entered network [169.254.1.0] [255.255.255.0] area 2 to add loopbacks to the area 2.
- 18. Repeated step 2 for all addresses connected in area 2 seen in Appendix A.

Implemented EIGRP

Enhanced Interior Gateway Protocol (EIGRP) was configured on all routers in the network to allow them to exchange routing information with each other. Each instance of

EIGRP is assigned an Autonomous System Number (ASN) as shown below- in this case the ASN was 2.

- 1. Entered conf t
- 2. Entered router eigrp [2]
- 3. Entered no auto-summary
- 4. Entered network [192.168.254.0] [0.0.0.0]
 - a. Repeated steps 1-5 on all routers- See Appendix A for EIGRP information.

Configured Redistribution and license enabling

Due to two different routing protocols being used in the same network topology, redistribution needed to be implemented to allow the routing protocols to communicate to each other.

- Entered license right-to-use activate ipservices accepteula to activate the license.
- 2. Entered conf t
- 3. Used license boot level ipservices to enable IPservices.
- 4. Logged into the Cisco 2901b.
- 5. Entered conf t
- 6. Used router eigrp 2 to enter EIGRP settings.
- 7. Entered redistribute ospf 2 metric 1 1 1 1 to set the OSPF redistribution.
- 8. Entered router ospf 2 to enter OSPF settings.
- 9. Use redistribute eigrp 2 metric 1 subnets to set EIGRP redistribution.

- 10. Logged into the Cisco 3750a.
- 11. Entered conf t | router eigrp 102 to enter EIGRP settings.
- 12. Used redistribute ospf 2 metric 1 1 1 1 to redistribute OSPF.
- 13. Entered router ospf 2 to enter OSPF settings.
- 14. Used redistribute eigrp 102 metric 1 subnets to redistribute EIGRP.

Configured GLBP and NTP

Gateway redundancy protocols were used on routers to allow for multiple routers to host 1 gateway. In the event that 1 router were to go down, the other router would still host the gateway, and end devices would still be able to connect to the IP address.

- 1. Logged into the Cisco 2911A
- 2. Entered conf t.
- 3. Entered each VLAN sub interface with int gig0/1.[102,2002,3002].
- 4. Used glbp 102 ip 192.168. [7, 8, 9].254 to set a redundant gateway IP.
- 5. Logged into the Cisco 2901A
- 6. Entered conf t.
- 7. Entered each VLAN sub interface with int gig0/1.[102,2002,3002].
- 8. Used glbp 102 ip 192.168.[7,8,9].254 to set the redundant gateway IP.

Configured NTP

Each device's clock was synchronized to the CIT network by setting the device's Network Time Protocol (NTP) servers to CIT's NTP servers. Unfortunately, the time was

still inaccurate, so the timezone and daylight savings were taken into account with the following commands.

- 9. Entered conf t
- 10. Entered ntp server 10.2.1.11
- 11. Entered ntp server 10.2.1.12
- 12. Entered clock timezone EST -5
- 13. Entered clock summer-time EDT recurring 2 Sun Mar 2:00 1 Sun Nov 2:00
- 14. Entered ntp update-calendar
 - a. Repeated steps 1-6 on all devices

Configured ICMP Strings

To view and modify devices from the SNMP monitoring software, configurations needed to be made on each device. These specified permissions for each user group. The public was set to "read-only", while private was set to "read-write".

- 1. Entered conf t
- 2. Entered snmp-server community public RO
- 3. Entered snmp-server community private RW
- 4. Entered wr

Configured SNMP monitoring on LibreNMS

Network management protocols can be used to monitor the status and issues within a network. The management protocol that was used was SNMP using LibreNMS on an Alma Linux VM.

Docker installation

- 1. Opened a Terminal window in the Alma Linux 9 Virtual Machine.
- 2. Used sudo yum install -y yum-utils.
- 3. Typed sudo yum-config0manager \ --add-repo \
 https://download.docker.com/linux/centos/docker-ce.repo to add
 the repository.
- 4. Entered sudo yum install docker-ce docker-ce-cli containerd.io docker-buildx-plugin docker-compose-plugin to install docker from the repo.
- 5. Started docker with sudo systematl start docker.

LibreNMS

- 6. Used sudo mkdir librenms to make a folder for LibreNMS.
- 7. Entered the folder with cd.
- 8. Used wget

https://github.com/librenms/docker/archive/refs/heads/master.zip to get the LibreNMS docker image.

- 9. Typed unzip master.zip to unzip the file.
- 10. Used cd docker-master/examples/compose.
- 11. Started docker with docker compose up -d.

- 12. Opened a Firefox tab and searched http://localhost:8000 to get to the Web GUI.
- 13. Clicked 'Devices' | 'Add a device' and added all devices by their loopback addresses.

Configured 6504 as DHCP Server

A DHCP server was implemented so that static IP addresses did not need to be set on the machines for them to have internet. This was done on the uplink layer 3 switch so that it could reach both sides equally.

- 1. Entered conf t
- 2. Used ip dhcp pool right-1002 to define the right 1002 DHCP pool.
- 3. Typed network 192.168.10.0 255.255.255.0 to define a range of IP addresses to serve out.
- 4. Used default-router 192.168.10.1 to set the default route.
- 5. Entered dns-server 10.2.1.11 10.2.1.12 to add both CIT DNS servers.
 - a. Repeated steps 1-5 for each side and each VLAN on the network. IP addressing information can be seen in Appendix A.
- 6. Used ip dhcp excluded-address 192.168.[4-12].1 192.168.[4-12].10 to exclude the first 10 addresses in each subnet for networking device interconnects and gateways.

Configured Additional DHCP Servers

DHCP servers needed to be configured in the EIGRP autonomous systems to be able to reach past OSPF into a second routing protocol. This was done on the 3750C and the 1921a.

1. Entered conf t on the 3750A.

- 2. Used ip dhcp pool VLAN3002 to set a DHCP pool.
- 3. Entered network 192.168.15.0 255.255.255.0 to set a pool of IP addresses.
- 4. Used default-router 192.168.15.1 to set the default route to be distributed.
- 5. Entered dns-server 10.2.1.11 10.2.1.12 to set DNS servers.
- 6. Entered conf t on the 1921a.
- 7. Used ip dhcp pool 1002 to create a DHCP pool.
- 8. Entered network 192.168.4.0 255.255.255.0 to create a pool of addresses.
- 9. Entered default-router 192.168.4.4 to set the default route.
- 10. Used dns-server 10.2.1.11 10.2.1.12 to set DNS servers.
- 11. Used ip dhcp excluded-address 192.168.4.1 192.168.4.10 to exclude the first 10 addresses.

CONCLUSIONS AND RECOMMENDATIONS

Ultimately, all requirements and expectations mentioned in the business scenario were fulfilled. Link State Routing and Layer 3 redundancy protocols were successfully implemented in the network with GLBP and OSPF. These protocols along with EIGRP provided network connectivity to all devices, with redistribution implemented to allow connectivity between the different routing protocols. Some recommendations for the future are included below.

Recommendation 1: Rather than implementing the network design in progressive phases, construct the network as one big phase. This way, physical network connections can be made all at once and an overarching network/IP scheme can be created to fulfill all requirements. Additionally, no network devices would need to be moved around to accommodate changes in future phases.

Recommendation 2: Focus on connectivity first and foremost. Once complete connectivity is established throughout the entire network for all devices, the following configurations are simple and will most likely be implemented successfully as devices that need to contact each other/outside networks are able to do so.

Recommendation 3: Spend more time/thought creating an all-encompassing network scheme. Carelessly throwing networks and subnetworks around will most likely result in conflicting or overlapping IP schemes, which are often hard to find and troubleshoot.

Conflicting IPs prevent one's devices from reaching exterior networks despite successfully pinging devices in the local area network.

RESULTS

By the end of this project, all network devices on all VLANs were successfully connected to both the outside network and all other LAN devices. 3 additional VLANs were created on top of the native VLAN, totaling 4 VLANs- 1, 1002, 2002, and 3002.

Additional EHWICs and a Double Wide were purchased with company funds and added to network devices to fulfill network requirements. This allowed fiber channel connections to be made, as well as more concurrent connections between network devices with a limited number of NICs, such as the 2901 routers. Three OSPF areas were created- 2 and 102, interconnected by area 0. Two additional EIGRP autonomous systems were created on either side of the OSPF areas- AS 2 and 102. Redistribution was configured to allow network connectivity between the two routing protocols.

The 6504 was configured as a DHCP server for all OSPF areas, and the 3750-C and 1921-A were configured as DHCP servers for their respective autonomous systems, totaling 3 DHCP servers serving out 192.168.X.0/24 networks for their respective VLANs. NTP was also configured on all network devices, and they all periodically backed up their config files to a TFTP server. LibreNMS was used for SNMP monitoring of all network devices from a central GUI. Resulting physical and logical diagrams of the network are provided in figures 3 and 4 below, respectively.




Figure 3: Physical Network Diagram




Figure 4: Logical Network Diagram

BIBLOGRAPHY

- GLBP Gateway Load Balancing Protocol. Cisco. (2009, August 6). Retrieved April 18, 2023, from https://www.cisco.com/en/US/docs/ios/12_2t/12_2t15/feature/guide/ft_glbp.html
- CIT Networking Laboratories: Laboratory Manual. (2019). Purdue University.
- D. Russo, personal communication, April 11, 2023
- Install Docker engine on centos. Docker Documentation. (2023, April 18). Retrieved April 18, 2023, from https://docs.docker.com/engine/install/centos/
- LibreNMS. (n.d.). *Docker*. Docker LibreNMS Docs. Retrieved April 18, 2023, from https://docs.librenms.org/Installation/Docker/
- Molenaar, R. (2020, May 19). *Basic ospf configuration*. NetworkLessons.com. Retrieved April 18, 2023, from https://networklessons.com/ospf/basic-ospf-configuration
- R. Deadman, personal communication, April 11, 2023
- Saputra, A. (2018, December 30). *Redistribute static route into EIGRP in Cisco IOS router*.

 MustBeGeek. Retrieved April 18, 2023, from https://www.mustbegeek.com/redistribute-static-route-into-eigrp-in-cisco-ios-router/
- Upravnik. (2022, December 18). *Configure Cisco Router as DHCP Server*. Study CCNA.

 Retrieved April 18, 2023, from https://study-ccna.com/configure-cisco-router-as-dhcp-server/

Wireshark. (2023). Wireshark (Version 3.6.5) [Computer software].

https://www.wireshark.org/download.html#spelunking

APPENDIX A: PROBLEM SOLVING

Problem 1: VLAN 1002

Problem Description: When attempting to create 4 Virtual Local Area Networks following the network design with VLAN numbers 1002, 2002, and 3002, VTP needed to be set to transparent mode to allow for VLAN numbers greater than 1000. Unfortunately, it was discovered that Cisco devices used VLANs 1002-1005 for token ring and FDDI. These VLANs were reserved and unable to be deleted.

Possible Solutions: Possible solutions included: 1) removing VLAN 1002- since its token ring/FDDI function was not planning to be used, 2) attaching the FDDI/Token Ring function of the to a different VLAN- since that VLAN served some purpose despite not currently being in use, and 3) using a different VLAN ID.

Solutions Attempted: Of the possible solutions, solutions attempted included: 1) removing VLAN 1002 via CLI with the commands "no int vlan 1002" and "no vlan 1002", which returned the error that this VLAN was unable to be removed, 2) editing VLAN 1002 via CLI with the commands "vlan 1002" and "no fddi-default", and 3) using VLAN 102 instead.

Final Solution: Ultimately, the solution that worked was 3) simply using a different VLAN ID. VLAN 102 was used instead of VLAN 1002, since VLAN ID numbers are somewhat arbitrary and the number used doesn't matter, as long as it remains consistent across devices. This was done with the commands "vlan 102" and "int vlan 102" on the CLI of all devices.

Problem 2: Duplicate Addressing

Problem Description: The same /24 networks that were assigned to devices the OSPF areas were also assigned to devices in EIGRP autonomous systems (AS). This caused confusion as all network devices were able to ping each other's interfaces, loopback addresses, and outside networks- but no hosts could access the internet. VLAN 1002 was assigned the 192.168.12.0/24 network, 192.168.22.0/24 assigned to VLAN 2002, and 192.168.32.0/24 to VLAN 3002.

Possible Solutions: Possible solutions included: 1) adding networks missing from OSPF/EIGRP- since some devices were able to access the internet but not others, 2) fixing problems with redistribution between OSPF and EIGRP- since hosts connected to an EIGRP AS were unable to access the network, and 3) providing separate /24 network spaces to each OSPF area and EIGRP AS.

Solutions Attempted: Of the possible solutions, solutions attempted included: 1) adding the loopback network into all devices' OSPF configurations- which enabled loopback pinging between devices but were still unable to access the internet, 2) entering the OSPF instance number (2) into the redistribution command instead of the OSPF area number (102)- which resolved some inter-device pinging but hosts were still unable to ping out to the internet, and 3) creating separate network spaces.

Final Solution: Ultimately, the solution that worked was 3) creating separate /24 networks for each VLAN in each OSPF area/EIGRP AS. This was done by creating 3 unique /24

networks in each AS/area- one for each VLAN. As a result, 3 /24 networks were assigned to area 0, 3 to area 2, 3 to area 102, 3 to AS 2, and 3 to AS 102. This solved the issue because the problem was ultimately to do with overlapping addresses, and creating separate address spaces prevented this from happening.

Problem 3: No Connectivity on 3750-A

Problem Description: After successfully configuring all devices and their connections to implement the desired network design, all devices in EIGRP AS 102 were unable to ping out, access the internet, or ping anything other than their directly connected interfaces. This was only an issue on the layer 3 switch (3750-A) on the left side of the network. Devices before this switch were able to ping all other devices, and devices beyond this switch were unable to ping out.

Possible Solutions: Possible solutions included: 1) configuring all connected interfaces to routing mode- since these interfaces needed to perform routing functions, 2) removed GLBP from OSPF area 102- since the ports needed to be trunked to implement GLBP which conflicts with its layer 3 functions, and 3) removed the "stub" configuration from OSPF-since this would restrict which LSAs were sent.

Solutions Attempted: Of the possible solutions, solutions attempted included: 1) configuring all interfaces to layer 3 routing mode by entering the "no switchport" command and assigning each interface a /30 IP, 2) removing GLBP from OSPF area 102 by entering

configure terminal mode on the interface and entering "no glbp", and 3) removing the "stub" configuration from OSPF.

Final Solution: Ultimately, the solution that worked was a combination of 1) configuring all interfaces of the 3750-A as a layer 3 switch, 2) removing GLBP from OSPF area 102, and 3) removing the "stub" configuration from OSPF. This was done by changing the licensing to an elevated version- since the current license was restrictive and did not allow for the removal of the stub configuration. These solutions worked because configuring interfaces as layer 3 allowed for appropriate routing, and removing the stub configuration allowed for required LSAs to be forwarded.

APPENDIX B: TABLES

Table 1: 2811 Console Cabling

Device	Interface	Cable	Interface	Device
Cisco 2811	Console	Patch Cable	COM1	PC1

 Table 2: Octal Console Cabling

Device	Interface	Cable	Interface	Device
TERM Server	ASYNC-16	Octal ASYNC	Console	2911-A
-	-	-	Console	2911-B
-	-	-	Console	2901-A
-	-	-	Console	2901-B
-	-	-	Console	1921-A
-	-	-	Console	3750-A
-	-	-	Console	3750-B
-	-	-	Console	6504

Table 3: Term Server Menu Mapping

Command #	Port Value	Device Name
1	2002	2911r1
2	2003	3750s1
3	2004	2911r2
4	2005	1921r3
5	2006	3750s2
6	2007	2901r4
7	2008	6504r5
8	2009	2901r6

Table 4: IOS Files

2911-A c2900-universalk9-mz.SPA.157-3.M4b.bin 2911-B c2900-universalk9-mz.SPA.157-3.M4b.bin 2901-A c2900-universalk9-mz.SPA.156-3.M8.bin 2901-B c2900-universalk9-mz.SPA.156-3.M8.bin 3750-A c3750e-universalk9-mz.152-4.E10.bin 3750-B c3750e-universalk9-mz.152-4.E10.bin 6504 s72033-adventerprisek9-mz.151-2.SY16.bin	Device	Image Filename
2901-A c2900-universalk9-mz.SPA.156-3.M8.bin 2901-B c2900-universalk9-mz.SPA.156-3.M8.bin 3750-A c3750e-universalk9-mz.152-4.E10.bin 3750-B c3750e-universalk9-mz.152-4.E10.bin	2911-A	c2900-universalk9-mz.SPA.157-3.M4b.bin
2901-B c2900-universalk9-mz.SPA.156-3.M8.bin 3750-A c3750e-universalk9-mz.152-4.E10.bin 3750-B c3750e-universalk9-mz.152-4.E10.bin	2911-B	c2900-universalk9-mz.SPA.157-3.M4b.bin
3750-A c3750e-universalk9-mz.152-4.E10.bin c3750e-universalk9-mz.152-4.E10.bin	2901-A	c2900-universalk9-mz.SPA.156-3.M8.bin
3750-B c3750e-universalk9-mz.152-4.E10.bin	2901-В	c2900-universalk9-mz.SPA.156-3.M8.bin
	3750-A	c3750e-universalk9-mz.152-4.E10.bin
6504 s72033-adventerprisek9-mz.151-2.SY16.bin	3750-В	c3750e-universalk9-mz.152-4.E10.bin
1	6504	s72033-adventerprisek9-mz.151-2.SY16.bin

Table 5: Network Cabling Information

Device	Interface	Cable	Interface	Device
6504	g1/3	Patch Cable	Uplink	-
6504	g1/2	Fiber cable	g0/0	2911-A
6504	g1/1	Fiber cable	g0/0	2901-A
2911-A	g0/1	Patch Cable	g2/1	3750-В
2911-A	g0/0	Patch Cable	g0/0	2901-B
2901-В	g0/1	Patch Cable	g1/1	3750-C
2901A	g0/1	Patch Cable	g2/3	3750-B
2901A	g0/2/0	Patch Cable	g0/0/0	2911-B
2901-A	g0/0	Patch Cable	g2/1	3750-A
2911-B	g0/1	Patch Cable	g2/3	3750-A
3750-A	g2/5	Patch Cable	g0/0	1921-A
1921-A	g0/1	Patch Cable	Ethernet	PC1
3750-C	g1/3	Patch Cable	Ethernet	PC2
2901-В	g0/3/7	Patch Cable	Ethernet	PC3

Table 6: Loopback Addressing Information

Device	Loopback Address	Subnet Mask

Link State Routing

Term Server	10.10.10.10	/32
2901-A	169.254.1.101	/32
2901-В	169.254.1.103	/32
2911-A	169.254.1.96	/32
2911-В	169.254.1.98	/32
3750-A	169.254.1.97	/32
3750-В	169.254.1.100	/32
6504	169.254.1.102	/32

Table 7: Interface Addressing Information

Device	Interface	IP Address	Subnet Mask
6504	g1/3	10.21.2.3	255.255.255.0
	g1/2	192.168.254.1	255.255.255.252
	g1/1	192.168.254.5	255.255.255.252
1921a	g0/0	192.168.254.30	255.255.255.252
	g0/1	192.168.4.4	255.255.255.0
3750a	g2/0/1	192.168.254.22	255.255.255.252
	g2/0/3	192.168.254.26	255.255.255.252
	g2/0/5	192.168.254.29	255.255.255.252
2911b	g0/1	192.168.254.25	255.255.255.252

Link State Routing

	g0/0/0	192.168.254.14	255.255.255.252
	g0/1.1002	192.168.4.1	255.255.255.0
	g0/1.2002	192.168.5.1	255.255.255.0
	g0/1.3002	192.168.6.1	255.255.255.0
2901a	g0/0	192.168.254.21	255.255.255.252
	g0/0/0	192.168.254.6	255.255.255.252
	g0/2/0	192.168.254.13	255.255.255.252
	g0/1.102	192.168.7.1	255.255.255.0
	g0/1.2002	192.168.8.1	255.255.255.0
	g0/1.3002	192.168.9.1	255.255.255.0
2911a	g0/0	192.168.254.9	255.255.255.252
	g0/0/0	192.168.254.2	255.255.255.252
	g0/1.102	192.168.7.2	255.255.255.0
	g0/1.2002	192.168.8.2	255.255.255.0
	g0/1.3002	192.168.9.2	255.255.255.0
2901b	g0/0	192.168.254.10	255.255.255.252
	g0/1	192.168.254.17	255.255.255.252
3750c	g1/0/1	192.168.254.18	255.255.255.252

Table 8a: OSPF network information

Device	OSPF Network

6504	169.254.1.0 0.0.0.255 area 0
	192.168.[7,8,9].0 0.0.0.255 area 0
	192.168.254.0 0.0.0.3 area 0
	192.168.254.4 0.0.0.3 area 0
3750A	169.254.1.0 0.0.0.255 area 102
	192.168.[4,5,6].0 0.0.0.255 area 102
	192.168.254.20 0.0.0.3 area 102
	192.168.254.24 0.0.0.3 area 102
2911B	169.254.1.0 0.0.0.255 area 102
	192.168.[7,8,9].0 0.0.0.255 area 0
	192.168.254.12 0.0.0.3 area 102
	192.168.254.24 0.0.0.3 area 102
2901A	169.254.1.0 0.0.0.255 area 0
	192.168.[4,5,6].0 0.0.0.255 area 102
	192.168.[7,8,9].0 0.0.0.255 area 0
	192.168.254.4 0.0.0.3 area 0
	192.168.254.12 0.0.0.3 area 102
	192.168.254.20 0.0.0.3 area 102
2911A	169.254.1.0 0.0.0.255 area 0
	169.254.1.0 0.0.0.255 area 2
	192.168.[7,8,9].0 0.0.0.255 area 0
	192.168.[10,11,12].0 0.0.0.255 area
	2

	192.168.254.0 0.0.0.3 area 0
	192.168.254.8 0.0.0.3 area 2
2901B	169.254.1.0 0.0.0.255 area 2
	192.168.11.0 0.0.0.255 area 2
	192.168.254.8 0.0.0.3 area 2

Table 8b: EIGRP network information

Device	EIGRP Network
1921a	169.254.1.0 0.0.0.255
	192.168.[4,5,6].0 0.0.0.255
	192.168.254.28 0.0.0.3
3750a	169.254.1.0 0.0.0.255
	192.168.254.28 0.0.0.3
3750c	169.254.1.0 0.0.0.255
	192.168.[13,14,15].0 0.0.0.255
	192.168.254.16 0.0.0.3
2901b	169.254.1.0 0.0.0.255
	192.168.[13,14,15].0 0.0.0.255
	192.168.254.16 0.0.0.3

Table 9: PC IP Addressing Information

IP Address	Subnet Mask	Gateway	DNS Servers
192.168.4.12	255.255.255.0	192.168.4.4	10.2.1.11,
			10.2.1.12
192.168.15.12	255.255.255.0	192.168.15.1	10.2.1.11,
192.168.12.12	255.255.255.0	192.168.12.1	10.2.1.12
			10.2.1.11,
			10.2.1.12
	192.168.4.12 192.168.15.12	192.168.4.12 255.255.255.0 192.168.15.12 255.255.255.0	192.168.4.12

Table 10: DHCP Information

DHCP	IP Pool	Network	Subnet Mask	Gateway	DNS
Server	Name				Servers
6504	Right-1002	192.168.10.0	255.255.255.0	192.168.10.1	10.2.1.11,
	Right-2002	192.168.11.0	255.255.255.0	192.168.11.1	10.2.1.12
	Right-3002	192.168.12.0	255.255.255.0	192.168.12.1	
	Mid-1002	192.168.7.0	255.255.255.0	192.168.7.1	
	Mid-2002	192.168.8.0	255.255.255.0	192.168.8.1	
	Mid-3002	192.168.9.0	255.255.255.0	192.168.9.1	
	Left-1002	192.168.4.0	255.255.255.0	192.168.4.1	

Link State Routing

	Left-2002	192.168.5.0	255.255.255.0	192.168.5.1	
	Left-3002	192.168.6.0	255.255.255.0	192.168.6.1	
1921A	Left-1002	192.168.4.0	255.255.255.0	192.168.4.4	10.2.1.11,
3750C	Right-1002	192.168.14.0	255.255.255.0	192.168.14.1	10.2.1.12
	Right-2002	192.168.15.0	255.255.255.0	192.168.15.1	
	Right-3002	192.168.16.0	255.255.255.0	192.168.16.1	

APPENDIX C: ROUTER AND SWITCH CONFIGURATIONS

This section contains a full copy of all configured options in their final form from each device on the network.

2811 Term Server
Current configuration: 3620 bytes
Last configuration change at 21:51:31 UTC Wed Mar 8 2023 by g2
version 15.1
service timestamps debug datetime msec
service timestamps log datetime msec
service password-encryption
hostname G2TermServer
boot-start-marker
boot-end-marker
no aaa new-model
dot11 syslog
ip source-route

ip cef

ip domain name cit.lcl

ip host 2911r1 2002 10.10.10.10

ip host 3750s1 2003 10.10.10.10

ip host 2911r2 2004 10.10.10.10

ip host 1921r3 2005 10.10.10.10

ip host 3750s2 2006 10.10.10.10

ip host 2901r4 2007 10.10.10.10

ip host 6504r5 2008 10.10.10.10

ip host 2901r6 2009 10.10.10.10

no ipv6 cef

multilink bundle-name authenticated

voice-card 0

crypto pki token default removal timeout 0

license udi pid CISCO2811 sn FTX1045A0TL

archive

path tftp://192.168.52.12/\$h-\$t

```
Link State Routing
time-period 360
username g2 password 7 10420F1C0D
redundancy
ip ssh version 1
interface Loopback0
ip address 10.10.10.10 255.255.255.255
interface FastEthernet0/0
ip address 10.21.2.2 255.255.255.0
duplex auto
speed auto
interface FastEthernet0/1
no ip address
shutdown
duplex auto
speed auto
interface Async0/0/0
no ip address
```

Link State Routing
encapsulation slip
[shutdown interfaces removed for brevity]
ip forward-protocol nd
no ip http server
no ip http secure-server
ip route 0.0.0.0 0.0.0.0 10.21.2.1
menu cisco title ^C
Welcome Laura/Ethan. Another day, another 345 lab :(
To exit, CTRL+SHIFT+6 then press x.
^C
^C menu cisco prompt ^C
menu cisco prompt ^C
menu cisco prompt ^C Select an option
menu cisco prompt ^C Select an option ^C
menu cisco prompt ^C Select an option ^C menu cisco text e menu-exit

menu cisco text 1 login to 2911r1

menu cisco command 1 telnet 10.10.10.10 2002

menu cisco text 2 login to 3750s1

menu cisco command 2 telnet 10.10.10.10 2003

menu cisco text 3 login to 2911r2

menu cisco command 3 telnet 10.10.10.10 2004

menu cisco text 4 login to 1921r3

menu cisco command 4 telnet 10.10.10.10 2005

menu cisco text 5 login to 3750s2

menu cisco command 5 telnet 10.10.10.10 2006

menu cisco text 6 login to 2901r4

menu cisco command 6 telnet 10.10.10.10 2007

menu cisco text 7 login to 6504r5

menu cisco command 7 telnet 10.10.10.10 2008

menu cisco text 8 login to 2901r6

menu cisco command 8 telnet 10.10.10.10 2009

menu cisco line-mode

Link State Routing control-plane mgcp profile default line con 0 password 7 060A092444 login local no exec line aux 0 login local no exec transport input telnet line 0/0/14 0/0/15 transport input telnet line vty 04 password 7 141B140E04 login local transport input ssh scheduler allocate 20000 1000 end

1921a

Current configuration: 1782 bytes

Last configuration change at 10:25:58 EDT Wed Apr 12 2023

NVRAM config last updated at 11:13:55 EDT Wed Apr 12 2023

version 15.4

service timestamps debug datetime msec

service timestamps log datetime msec

no service password-encryption

hostname 1921a

boot-start-marker

boot-end-marker

no aaa new-model

clock timezone EST -5 0

clock summer-time EDT recurring

ip dhcp excluded-address 192.168.4.1 192.168.4.10

ip dhcp pool 1002

network 192.168.4.0 255.255.255.0

default-router 192.168.4.4

dns-server 10.2.1.11 10.2.1.12

ip cef

Link State Routing no ipv6 cef multilink bundle-name authenticated cts logging verbose license udi pid CISCO1921/K9 sn FJC2144L1V3 archive path tftp://192.168.15.2/\$h-\$t time-period 360 vtp mode transparent redundancy interface Loopback0 ip address 169.254.1.99 255.255.255.255 interface Embedded-Service-Engine0/0 no ip address shutdown interface GigabitEthernet0/0

interface GigabitEthernet0/0
description "3750A"
ip address 192.168.254.30 255.255.255.252
duplex auto

Link State Routing speed auto interface GigabitEthernet0/1 ip address 192.168.4.4 255.255.255.0 duplex auto speed auto router eigrp 102 network 169.254.1.0 0.0.0.255 network 192.168.4.0 network 192.168.5.0 network 192.168.6.0 network 192.168.254.28 0.0.0.3 ip forward-protocol nd no ip http server

no ip http server
no ip http secure-server
snmp-server community public RO
snmp-server community private RW

control-plane

line con 0
line aux 0
line 2
no activation-character
no exec
transport preferred none
transport output pad telnet rlogin lapb-ta mop udptn v120 ssh
stopbits 1
line vty 0 4
login
transport input none
scheduler allocate 20000 1000
ntp update-calendar
ntp server 10.2.1.11
ntp server 10.2.1.12
End

	_	-
74	~	1 _

2901a
Current configuration: 2574 bytes
Last configuration change at 11:01:36 EDT Wed Apr 12 2023
NVRAM config last updated at 19:06:43 EDT Tue Apr 11 2023
version 15.6
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
hostname 2901a
boot-start-marker
boot-end-marker
no aaa new-model
clock timezone EST -5 0

clock summer-time EDT recurring

Link State Routing ip cef no ipv6 cef multilink bundle-name authenticated license udi pid CISCO2901/K9 sn FTX164583HE archive path tftp://192.168.15.2/\$h-\$t time-period 360 vtp mode transparent redundancy interface Loopback0 ip address 169.254.1.101 255.255.255.255 interface Embedded-Service-Engine0/0 no ip address shutdown interface GigabitEthernet0/0 description "3750A" ip address 192.168.254.21 255.255.255.252

duplex auto

speed auto

interface GigabitEthernet0/1

description "3750B"

no ip address

duplex auto

speed auto

interface GigabitEthernet0/1.102

description "VLAN 102"

encapsulation dot1Q 102

ip address 192.168.7.1 255.255.255.0

ip helper-address 169.254.1.102

glbp 102 ip 192.168.7.254

interface GigabitEthernet0/1.2002

description "VLAN 2002"

encapsulation dot1Q 2002

ip address 192.168.8.1 255.255.255.0

ip helper-address 169.254.1.102

glbp 202 ip 192.168.8.254

interface GigabitEthernet0/1.3002

description "VLAN 3002"

encapsulation dot1Q 3002

ip address 192.168.9.1 255.255.255.0

ip helper-address 169.254.1.102

glbp 302 ip 192.168.9.254

interface GigabitEthernet0/0/0

description "6504"

ip address 192.168.254.6 255.255.255.252

interface GigabitEthernet0/2/0

description "2911B"

ip address 192.168.254.13 255.255.255.252

router ospf 2

network 169.254.1.0 0.0.0.255 area 0

network 192.168.4.0 0.0.0.255 area 102

network 192.168.5.0 0.0.0.255 area 102

network 192.168.6.0 0.0.0.255 area 102

network 192.168.7.0 0.0.0.255 area 0

network 192.168.8.0 0.0.0.255 area 0

network 192.168.9.0 0.0.0.255 area 0

line vty 04

network 192.168.254.4 0.0.0.3 area 0 network 192.168.254.12 0.0.0.3 area 102 network 192.168.254.20 0.0.0.3 area 102 ip forward-protocol nd no ip http server no ip http secure-server snmp-server community public RO snmp-server community private RW control-plane line con 0 line aux 0 line 2 no activation-character no exec transport preferred none transport output pad telnet rlogin lapb-ta mop udptn v120 ssh stopbits 1

login

transport input none

scheduler allocate 20000 1000

ntp update-calendar

ntp server 10.2.1.11

ntp server 10.2.1.12

End

2901b

Current configuration: 2828 bytes
Last configuration change at 10:26:22 EDT Wed Apr 12 2023
NVRAM config last updated at 19:06:40 EDT Tue Apr 11 2023
version 15.7
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
hostname 2901b
boot-start-marker
boot-end-marker
no aaa new-model
clock timezone EST -5 0
clock summer-time EDT recurring
ip cef
no ipv6 cef

Link State Routing multilink bundle-name authenticated voice-card 0 vxml logging-tag license udi pid CISCO2901/K9 sn FTX1502802W license boot module c2900 technology-package datak9 hw-module pvdm 0/0 archive path tftp://192.168.15.2/\$h-\$t time-period 360 vtp mode transparent redundancy vlan 102,2002,3002 interface Loopback0 ip address 169.254.1.103 255.255.255.255 interface Embedded-Service-Engine0/0

no ip address

Link State Routing shutdown interface GigabitEthernet0/0 description "To 2911A" ip address 192.168.254.10 255.255.255.252 duplex auto speed auto interface GigabitEthernet0/1 description "To 3750C" ip address 192.168.254.17 255.255.255.252 duplex auto speed auto interface GigabitEthernet0/0/0 no ip address duplex auto speed auto interface GigabitEthernet0/3/0

 $interface\ GigabitEthernet 0/3/1$

no ip address

Link State Routing no ip address interface GigabitEthernet0/3/2 no ip address interface GigabitEthernet0/3/3 no ip address interface GigabitEthernet0/3/4 no ip address interface GigabitEthernet0/3/5 no ip address interface GigabitEthernet0/3/6 no ip address interface GigabitEthernet0/3/7 description "PC3" switchport mode access no ip address interface Vlan1

```
Link State Routing
```

description "VLAN 2002"

ip address 192.168.11.1 255.255.255.0

ip helper-address 10.21.2.3

router eigrp 2

network 169.254.1.0 0.0.0.255

network 192.168.13.0

network 192.168.14.0

network 192.168.15.0

network 192.168.254.16 0.0.0.3

redistribute ospf 2 metric 1 1 1 1 1

router ospf 2

redistribute eigrp 2 metric 1 subnets

network 169.254.1.0 0.0.0.255 area 2

network 192.168.11.0 0.0.0.255 area 2

network 192.168.254.8 0.0.0.3 area 2

ip forward-protocol nd

no ip http server

no ip http secure-server

Link State Routing
snmp-server community public RO
snmp-server community private RW
control-plane
mgcp behavior rsip-range tgcp-only
mgcp behavior comedia-role none
mgcp behavior comedia-check-media-src disable
mgcp behavior comedia-sdp-force disable
mgcp profile default
gatekeeper
shutdown
vstack
line con 0
line aux 0
line 2
no activation-character
no exec
transport preferred none

```
Link State Routing

transport output pad telnet rlogin lapb-ta mop udptn v120 ssh
stopbits 1
line vty 0 4

login

transport input none

scheduler allocate 20000 1000
ntp update-calendar
ntp server 10.2.1.11
ntp server 10.2.1.12
```

End

2911a

Current configuration: 2942 bytes

Last configuration change at 11:00:15 EDT Wed Apr 12 2023

NVRAM config last updated at 19:06:43 EDT Tue Apr 11 2023

version 15.7

service timestamps debug datetime msec

service timestamps log datetime msec

no service password-encryption

hostname 2911a

boot-start-marker

boot-end-marker

no aaa new-model

clock timezone EST -5 0

clock summer-time EDT recurring

ip domain name cit.lcl

ip cef

Link State Routing no ipv6 cef multilink bundle-name authenticated voice-card 0 vxml logging-tag license udi pid CISCO2911/K9 sn FTX1631AKEZ archive path tftp://192.168.15.2/\$h-\$t time-period 360 redundancy interface Loopback0 ip address 169.254.1.96 255.255.255.255 interface Embedded-Service-Engine0/0 no ip address shutdown interface GigabitEthernet0/0 description "To 2901B"

```
Link State Routing
```

ip address 192.168.254.9 255.255.255.252

duplex auto

speed auto

interface GigabitEthernet0/1

no ip address

duplex auto

speed auto

interface GigabitEthernet0/1.102

description "VLAN 1002"

encapsulation dot1Q 102

ip address 192.168.7.2 255.255.255.0

ip helper-address 169.254.1.102

glbp 102 ip 192.168.7.254

interface GigabitEthernet0/1.2002

description "VLAN 2002"

encapsulation dot1Q 2002

ip address 192.168.8.2 255.255.255.0

ip helper-address 169.254.1.102

glbp 202 ip 192.168.8.254

```
Link State Routing
```

interface GigabitEthernet0/1.3002

description "VLAN 3002"

encapsulation dot1Q 3002

ip address 192.168.9.2 255.255.255.0

ip helper-address 169.254.1.102

glbp 302 ip 192.168.9.254

interface GigabitEthernet0/2

no ip address

duplex auto

speed auto

interface GigabitEthernet0/0/0

description "Fiber to 6504"

ip address 192.168.254.2 255.255.255.252

router ospf 2

network 169.254.1.100 0.0.0.0 area 0

network 169.254.1.102 0.0.0.0 area 0

network 169.254.1.103 0.0.0.0 area 2

network 169.254.1.0 0.0.0.255 area 2

network 192.168.7.0 0.0.0.255 area 0

network 192.168.8.0 0.0.0.255 area 0

network 192.168.9.0 0.0.0.255 area 0

network 192.168.10.0 0.0.0.255 area 2

network 192.168.11.0 0.0.0.255 area 2

network 192.168.12.0 0.0.0.255 area 2

network 192.168.254.0 0.0.0.3 area 0

network 192.168.254.8 0.0.0.3 area 2

ip forward-protocol nd

no ip http server

no ip http secure-server

ipv6 ioam timestamp

snmp-server community public RO

snmp-server community private RW

control-plane

mgcp behavior rsip-range tgcp-only

mgcp behavior comedia-role none

mgcp behavior comedia-check-media-src disable

mgcp behavior comedia-sdp-force disable

Link State Routing
mgcp profile default
gatekeeper
shutdown
vstack
line con 0
line aux 0
line 2
no activation-character
no exec
transport preferred none
transport output lat pad telnet rlogin lapb-ta mop udptn v120 ssh
stopbits 1
line vty 0 4
login
transport input none
scheduler allocate 20000 1000
ntp update-calendar

ntp server 10.2.1.11

ntp server 10.2.1.12

End

no ipv6 cef

2911b

Current configuration: 2342 bytes Last configuration change at 11:11:25 EDT Mon Apr 17 2023 NVRAM config last updated at 19:06:41 EDT Tue Apr 11 2023 version 15.7 service timestamps debug datetime msec service timestamps log datetime msec no service password-encryption hostname 2911b boot-start-marker boot-end-marker no aaa new-model clock timezone EST -5 0 clock summer-time EDT recurring ip cef

multilink bundle-name authenticated

license udi pid CISCO2911/K9 sn FTX1821ALC6

archive

path tftp://192.168.15.2/\$h-\$t

time-period 360

redundancy

interface Loopback0

ip address 169.254.1.98 255.255.255.255

 $interface\ Embedded\text{-}Service\text{-}Engine0/0$

no ip address

shutdown

interface GigabitEthernet0/0

no ip address

duplex auto

speed auto

interface GigabitEthernet0/1

ip address 192.168.254.25 255.255.255.252

duplex auto

speed auto

interface GigabitEthernet0/1.202

interface GigabitEthernet0/1.302

interface GigabitEthernet0/1.1002

description "VLAN 1002"

encapsulation dot1Q 102

ip address 192.168.4.1 255.255.255.0

ip helper-address 169.254.1.102

interface GigabitEthernet0/1.2002

description "VLAN 2002"

encapsulation dot1Q 2002

ip address 192.168.5.1 255.255.255.0

ip helper-address 169.254.1.102

interface GigabitEthernet0/1.3002

description "VLAN 3002"

```
Link State Routing
```

encapsulation dot1Q 3002

ip address 192.168.6.1 255.255.255.0

ip helper-address 169.254.1.102

interface GigabitEthernet0/2

no ip address

duplex auto

speed auto

interface GigabitEthernet0/0/0

description "2901A"

ip address 192.168.254.14 255.255.255.252

router ospf 2

network 169.254.1.0 0.0.0.255 area 102

network 192.168.7.0 0.0.0.255 area 0

network 192.168.8.0 0.0.0.255 area 0

network 192.168.9.0 0.0.0.255 area 0

network 192.168.254.12 0.0.0.3 area 102

network 192.168.254.24 0.0.0.3 area 102

ip forward-protocol nd

Link State Routing no ip http server no ip http secure-server snmp-server community public RO snmp-server community private RW control-plane line con 0 line aux 0 line 2 no activation-character no exec transport preferred none transport output pad telnet rlogin lapb-ta mop udptn v120 ssh stopbits 1 line vty 0 4 login transport input none scheduler allocate 20000 1000 ntp update-calendar ntp server 10.2.1.11

ntp server 10.2.1.12

End

27500	
3/30a	

Current configuration: 5525 bytes

Last configuration change at 11:13:01 EDT Mon Apr 17 2023

NVRAM config last updated at 11:10:29 EDT Wed Apr 12 2023

version 15.2

no service pad

service timestamps debug datetime msec

service timestamps log datetime msec

no service password-encryption

hostname 3750A

boot-start-marker

boot-end-marker

username g2

no aaa new-model

clock timezone EST -5 0

clock summer-time EDT recurring

switch 2 provision ws-c3750e-48pd

system mtu routing 1500

ip routing

vtp mode transparent

crypto pki trustpoint TP-self-signed-201719040

enrollment selfsigned

subject-name cn=IOS-Self-Signed-Certificate-201719040

revocation-check none

rsakeypair TP-self-signed-201719040

crypto pki certificate chain TP-self-signed-201719040

certificate self-signed 01

30820229 30820192 A0030201 02020101 300D0609 2A864886 F70D0101 05050030 30312E30 2C060355 04031325 494F532D 53656C66 2D536967 6E65642D 43657274 69666963 6174652D 32303137 31393034 30301E17 0D303630 31303230 30303135 305A170D 32303031 30313030 30303030 5A303031 2E302C06 03550403 1325494F 532D5365 6C662D53 69676E65 642D4365 72746966 69636174 652D3230 31373139 30343030 819F300D 06092A86 4886F70D 01010105 0003818D 00308189 02818100 BD9F7831 45CCFF4C 6D605967 ED2BFCF1 D8A82653 8AD18A9B F9410DC8 A5BDDF18

FAE99BFE DEF1A730 361C8779 20C02F04 901C941B DAEA4FE8 1A962A50

0ED17952

46DD388F 086A760A E4D60619 AE2C2C2D 4924B295 6C2FE4A8 867D079A

4DBA3631

7A76074D 80F3C799 A1428F51 29459572 A32FC5D7 5435D8E8 AFB81FC5

7B1BAFFD

02030100 01A35330 51300F06 03551D13 0101FF04 05300301 01FF301F 0603551D

23041830 16801497 620924A2 B70EAEA9 55BD9346 DC6216AA AF4BD430 1D060355

1D0E0416 04149762 0924A2B7 0EAEA955 BD9346DC 6216AAAF 4BD4300D

06092A86

4886F70D 01010505 00038181 009490B6 172E091B 6ADCAD84 7521BB3F B957E0B7

EBA9BC23 6068ACC0 D10D26A7 1D0E90A2 CB805D1F 33C5EDB0 B67A8519

35092BF2

D5E2DD1A 7A150DF8 99403D49 44E0CE70 EF38880E 17A4DA0A 7179E8C5

9B989C87

A65B9734 DEFCF342 A59DB3AB D0F57E2B 1A1AFE8E 7CAD5B70 C3AAD72A

D95C551A

04AEAF6A 38817C06 260A7F32 13

quit

license boot level ipservices

archive

path tftp://192.168.15.2/\$h-\$t

time-period 360

spanning-tree mode rapid-pvst spanning-tree extend system-id vlan internal allocation policy ascending vlan 102 name vlan102 vlan 2002 name vlan2002 vlan 3002 name vlan3002 interface Loopback0 ip address 169.254.1.97 255.255.255.255 interface FastEthernet0 no ip address no ip route-cache interface GigabitEthernet2/0/1

Link State Routing description "To 2901a" no switchport ip address 192.168.254.22 255.255.255.252 interface GigabitEthernet2/0/2 interface GigabitEthernet2/0/3 description "To 2911B" no switchport ip address 192.168.254.26 255.255.255.252 interface GigabitEthernet2/0/4 interface GigabitEthernet2/0/5 description "To 1921a" no switchport ip address 192.168.254.29 255.255.255.252 interface GigabitEthernet2/0/6 [removed for brevity] interface Vlan1

no ip address

interface Vlan102

ip address 192.168.4.2 255.255.255.0

interface Vlan2002

ip address 192.168.5.2 255.255.255.0

interface Vlan3002

ip address 192.168.6.2 255.255.255.0

router eigrp 102

network 169.254.1.0 0.0.0.255

network 192.168.254.28 0.0.0.3

redistribute ospf 2 metric 1 1 1 1 1

router ospf 2

redistribute eigrp 102 metric 1 subnets

network 169.254.1.0 0.0.0.255 area 102

network 192.168.4.0 0.0.0.255 area 102

 $network\ 192.168.5.0\ 0.0.0.255\ area\ 102$

network 192.168.6.0 0.0.0.255 area 102

network 192.168.254.20 0.0.0.3 area 102

Link State Routing network 192.168.254.24 0.0.0.3 area 102 ip forward-protocol nd ip http server ip http secure-server snmp-server community public RO snmp-server community private RW line con 0 password lfeh login line vty 04 login line vty 5 15 login ntp update-calendar

End

ntp server 10.2.1.11

ntp server 10.2.1.12

3750b

Current configuration: 3619 bytes

Last configuration change at 10:18:36 EDT Wed Apr 12 2023

version 15.2

no service pad

service timestamps debug datetime msec

service timestamps log datetime msec

service password-encryption

hostname c345-g2-3750b

boot-start-marker

boot-end-marker

username g2

no aaa new-model

clock timezone EST -5 0

clock summer-time EDT recurring

switch 2 provision ws-c3750e-48pd

system mtu routing 1500

vtp mode transparent archive path tftp://192.168.15.2/\$h-\$t time-period 360 spanning-tree mode rapid-pvst spanning-tree extend system-id vlan internal allocation policy ascending vlan 102 name vlan102 vlan 2002 name vlan2002 vlan 3002 name vlan3002 interface Loopback0 ip address 169.254.1.100 255.255.255.255

Link State Routing

interface FastEthernet0

no ip address

interface GigabitEthernet2/0/1

description "To 2911A"

switchport trunk allowed vlan 1,102,2002,3002

switchport trunk encapsulation dot1q

switchport mode trunk

interface GigabitEthernet2/0/2

interface GigabitEthernet2/0/3

description "To 2901A"

switchport trunk allowed vlan 1,102,2002,3002

switchport trunk encapsulation dot1q

switchport mode trunk

interface GigabitEthernet2/0/4

interface GigabitEthernet2/0/5

switchport access vlan 102

switchport mode access

Link State Routing interface GigabitEthernet2/0/6 interface GigabitEthernet2/0/7 switchport access vlan 2002 switchport mode access interface GigabitEthernet2/0/8 interface GigabitEthernet2/0/9 switchport access vlan 3002 switchport mode access interface GigabitEthernet2/0/10 [removed for brevity]

interface Vlan1

no ip address

interface Vlan102

ip address 192.168.7.5 255.255.255.0

Link State Routing interface Vlan2002 ip address 192.168.8.5 255.255.255.0 interface Vlan3002 ip address 192.168.9.5 255.255.255.0 ip default-gateway 10.21.2.1 ip forward-protocol nd ip http server ip http secure-server snmp-server community public RO snmp-server community private RW line con 0 password 7 04570D0307 login line vty 0 4 login line vty 5 15

login

ntp update-calendar

ntp server 10.2.1.11

ntp server 10.2.1.12

End

Current configuration: 5281 bytes

Last configuration change at 10:28:56 EDT Wed Apr 12 2023

version 15.2

no service pad

service timestamps debug datetime msec

service timestamps log datetime msec

service password-encryption

hostname c345-g2-3750c

boot-start-marker

boot-end-marker

username g2

no aaa new-model

clock timezone EST -5 0

clock summer-time EDT recurring

switch 1 provision ws-c3750e-48pd

system mtu routing 1500

```
Link State Routing
```

ip routing

ip dhcp excluded-address 192.168.12.1 192.168.12.10

ip dhcp pool VLAN3002

network 192.168.15.0 255.255.255.0

default-router 192.168.15.1

dns-server 10.2.1.11 10.2.1.12

vtp mode transparent

crypto pki trustpoint TP-self-signed-2545411584

enrollment selfsigned

subject-name cn=IOS-Self-Signed-Certificate-2545411584

revocation-check none

rsakeypair TP-self-signed-2545411584

crypto pki certificate chain TP-self-signed-2545411584

certificate self-signed 01

3082022B 30820194 A0030201 02020101 300D0609 2A864886 F70D0101 05050030

31312F30 2D060355 04031326 494F532D 53656C66 2D536967 6E65642D 43657274

69666963 6174652D 32353435 34313135 3834301E 170D3036 30313032 30303031 35325A17 0D323030 31303130 30303030 305A3031 312F302D 06035504 03132649 4F532D53 656C662D 5369676E 65642D43 65727469 66696361 74652D32 35343534 31313538 3430819F 300D0609 2A864886 F70D0101 01050003 818D0030 81890281 81009F95 FC80E7C9 66DE8508 BD5D9C4D C4B09320 0063C697 6D9433BE 192BB6CB

A9745B60 8710651C ECD3CB32 452C1708 99C6B2E2 CF9347F3 8B873B8E C03BD950

AA0473FA 17DE0A06 3B0EEB56 D930AF81 1F4F808B B3450F0B CDAB5545 B6AFAF82

453E47C3 75C1F6D1 A51DC03F 1F71E46D 7EB56BF7 706B6E5B BE1729FF 0D865E33

24010203 010001A3 53305130 0F060355 1D130101 FF040530 030101FF 301F0603
551D2304 18301680 145399D7 A10E6704 70D2855D 53AA5E72 3A56DCC4 02301D06
03551D0E 04160414 5399D7A1 0E670470 D2855D53 AA5E723A 56DCC402 300D0609
2A864886 F70D0101 05050003 8181005B 9DD4F32B 42940DE2 71DE839A 637F7590
EC2E5757 8EDED349 812FD145 C707699F CD80C3FB F54AB891 1E8962AC
2CCD70F3

4F5735BC 6DAE3D1A DD9E078F 380E6E86 09A2A507 5BB4B7E4 3704C888 D8B959B8

DF7B255A 53815253 CA33835E D17A6EE3 3C3F6835 A9D4C1D8 CC5B3EC4 D91B3BFA

DAB23180 57158979 BE3BC85A 73D675

Link State Routing quit license boot level ipservices archive path tftp://192.168.15.2/\$h-\$t time-period 360 spanning-tree mode rapid-pvst spanning-tree extend system-id vlan internal allocation policy ascending vlan 102 name vlan102 vlan 2002 name vlan2002 vlan 3002

ip address 169.254.1.104 255.255.255.255

name vlan3002

interface Loopback0

Link State Routing
interface FastEthernet0
no ip address
no ip route-cache
interface GigabitEthernet1/0/1
description "To 2901B"
no switchport
ip address 192.168.254.18 255.255.255.252
interface GigabitEthernet1/0/2
interface GigabitEthernet1/0/3
switchport access vlan 3002
switchport mode access
interface GigabitEthernet1/0/4
[removed for brevity]
interface Vlan1
no ip address
interface Vlan102

ip address 192.168.13.1 255.255.255.0

interface Vlan2002

ip address 192.168.14.1 255.255.255.0

interface Vlan3002

ip address 192.168.15.1 255.255.255.0

router eigrp 2

network 169.254.1.0 0.0.0.255

network 192.168.13.0

network 192.168.14.0

network 192.168.15.0

network 192.168.254.16 0.0.0.3

ip forward-protocol nd

ip http server

ip http secure-server

snmp-server community public RO

snmp-server community private RW

line con 0

password 7 000815030C

login

line vty 0 4

login

line vty 5 15

login

ntp update-calendar

ntp server 10.2.1.11

ntp server 10.2.1.12

End

6504

Current configuration: 7541 bytes

Last configuration change at 10:41:59 EDT Wed Apr 12 2023 by g2 NVRAM config last updated at 10:35:49 EDT Wed Apr 12 2023 by g2

version 15.1

service timestamps debug datetime msec

service timestamps log datetime msec

service password-encryption

service counters max age 5

hostname c345-g2-6504

boot-start-marker

boot system tftp s72033-adventerprisek9-mz.151-2.SY16.bin 255.255.255.255

boot system flash:s72033-adventerprisek9-mz.151-2.SY16.bin

boot system flash sup-bootdisk:s72033-adventerprisek9-mz.151-2.SY16.bin

boot-end-marker

username g2 password 7 11051F001F

no aaa new-model

clock timezone EST -5

clock summer-time EDT recurring

vtp mode transparent

ip dhcp excluded-address 192.168.10.1 192.168.10.10

ip dhcp excluded-address 192.168.11.1 192.168.11.10

ip dhcp excluded-address 192.168.12.1 192.168.12.10

ip dhcp excluded-address 192.168.4.1 192.168.4.10

ip dhcp excluded-address 192.168.5.1 192.168.5.10

ip dhcp excluded-address 192.168.6.1 192.168.6.10

ip dhcp excluded-address 192.168.7.1 192.168.7.10

ip dhcp excluded-address 192.168.8.1 192.168.8.10

ip dhcp excluded-address 192.168.9.1 192.168.9.10

ip dhcp pool right-1002

network 192.168.10.0 255.255.255.0

default-router 192.168.10.1

dns-server 10.2.1.11 10.2.1.12

ip dhcp pool right-2002

```
network 192.168.11.0 255.255.255.0 default-router 192.168.11.1 dns-server 10.2.1.11 10.2.1.12
```

ip dhcp pool right-3002 network 192.168.12.0 255.255.255.0

dns-server 10.2.1.11 10.2.1.12

default-router 192.168.12.1

ip dhcp pool left-1002

network 192.168.4.0 255.255.255.0

default-router 192.168.4.1

dns-server 10.2.1.11 10.2.1.12

ip dhcp pool left-2002

network 192.168.5.0 255.255.255.0

default-router 192.168.5.1

dns-server 10.2.1.11 10.2.1.12

ip dhcp pool left-3002

network 192.168.6.0 255.255.255.0

default-router 192.168.6.1

dns-server 10.2.1.11 10.2.1.12

```
ip dhcp pool mid-1002
 network 192.168.7.0 255.255.255.0
 default-router 192.168.7.1
 dns-server 10.2.1.11 10.2.1.12
ip dhcp pool mid-2002
 network 192.168.8.0 255.255.255.0
 default-router 192.168.8.1
 dns-server 10.2.1.11 10.2.1.12
ip dhcp pool mid-3002
 network 192.168.9.0 255.255.255.0
 default-router 192.168.9.1
 dns-server 10.2.1.11 10.2.1.12
ip domain-name cit.lcl
ipv6 unicast-routing
mls netflow interface
archive
path tftp://192.168.15.2/$h-$t
time-period 360
```

Link State Routing spanning-tree mode pvst spanning-tree extend system-id redundancy main-cpu auto-sync running-config mode sso vlan internal allocation policy ascending vlan access-log ratelimit 2000 vlan 102 name vlan1002 vlan 202 name vlan202

vlan 302

vlan 2002

name vlan2002

name vlan302

vlan 3002

name vlan3002

ip ssh version 2

interface Loopback0

ip address 169.254.1.102 255.255.255.255

interface GigabitEthernet1/1

description "Fiber to 2901A"

ip address 192.168.254.5 255.255.255.252

ip nat inside

interface GigabitEthernet1/2

description "Fiber to 2911A"

ip address 192.168.254.1 255.255.255.252

ip nat inside

interface GigabitEthernet1/3

description "CIT Uplink"

ip address 10.21.2.3 255.255.255.0

ip nat outside

```
interface TenGigabitEthernet1/4
no ip address
```

shutdown

[removed for brevity]

interface Vlan1

no ip address

shutdown

router ospf 2

redistribute static subnets

network 169.254.1.0 0.0.0.255 area 0

network 192.168.7.0 0.0.0.255 area 0

network 192.168.8.0 0.0.0.255 area 0

network 192.168.9.0 0.0.0.255 area 0

network 192.168.254.0 0.0.0.3 area 0

network 192.168.254.4 0.0.0.3 area 0

default-information originate

ip nat pool g2 10.21.2.3 10.21.2.3 netmask 255.255.255.0

ip nat inside source list 1 interface GigabitEthernet1/3 overload

Link State Routing ip nat inside source static 192.168.15.2 10.21.2.10 ip forward-protocol nd no ip http server no ip http secure-server ip route 0.0.0.0 0.0.0.0 10.21.2.1 access-list 1 permit 192.168.0.0 0.0.255.255 snmp-server community public RO snmp-server community private RW control-plane dial-peer cor custom line con 0 password 7 082D4A4B01 login line vty 0 4 password 7 082D4A4B01 login local

transport input ssh

ntp update-calendar

ntp server 10.2.1.11

ntp server 10.2.1.12

mac address-table aging-time 480

diagnostic bootup level minimal

end