1. 选择要刷的固件,有离线嗅探固件,有出厂固件以及 iceman 固件

in firmware_win

flasher.exe

libgcc_s_dw2-1.dll

in licemanade.bat

2. 刷离线教程



a) 输入端口号,端口号在设备管理器-端口可以看到,一直直到自动刷完固件位置



```
正在刷新 bootrom.elf,请等候片刻……

Loading ELF file 'firmware_win\bootrom-2.0.0-snoop-onlyHF.elf'...
Loading usable ELF segments:
0: U 0x00100000 P 0x00100000 (0x00000200-)0x000000200) [R X] 00x94
1: U 0x00200000 P 0x00100200 (0x00000b38->0x00000b38) [RWX] 00x298

Waiting for Proxmark to appear on com10. Found.
Entering bootloader...
(Press and release the button only to abort)
Waiting for Proxmark to reappear on com10..... Found.

Flashing...
Writing segments for file: firmware_win\bootrom-2.0.0-snoop-onlyHF.elf
0x00100000..0x001001ff [0x200 / 1 blocks]. OK
0x00100200..0x00100d37 [0xb38 / 6 blocks]..... OK

Resetting hardware...
All done.

Have a nice day!
```

```
正在刷新 fullimage.elf,请等候片刻……

Loading ELF file 'firmware_win\fullimage-2.0.0-snoop-onlyHF.elf'...
Loading usable ELF segments:

9: U 0x00102000 P 0x00102000 (0x0001497e->0x0001497e>) [R ] 00xb4

1: U 0x00118000 P 0x00118000 (0x00001cee1->0x00001cee1) [R X] 00x14a38

2: U 0x00200000 P 0x00134ee1 (0x000029c8->0x000029c8) [RWX] 00x31920

Note: Extending previous segment from 0x1cee1 to 0x1f8a9 bytes

Waiting for Proxmark to appear on com10. Found.

Entering bootloader...
(Press and release the button only to abort)
Waiting for Proxmark to reappear on com10..... Found.

Flashing...

Writing segments for file: firmware_win\fullimage-2.0.0-snoop-onlyHF.elf
0x00102000.0x0011697d [0x1497e / 165 blocks].

OK
0x00118000.0x001378a8 [0x1f8a9 / 253 blocks].
```

- 3. 刷 iceman 固件
 - a) 输入端口号



```
正在刷新 bootrom.elf,请等候片刻……

Loading ELF file 'firmware_win\bootrom-iceman.elf'...
Loading usable ELF segments:

0: U 0x00100000 P 0x00100000 (0x00000200-)0x000000200) [R X] 00x94
1: U 0x00200000 P 0x00100200 (0x00000080-)0x00000080) [RWX] 00x298

Waiting for Proxmark to appear on com10. Found.
Entering bootloader...
(Press and release the button only to abort)
Waiting for Proxmark to reappear on com10..... Found.

Plashing...
Writing segments for file: firmware_win\bootrom-iceman.elf
0x00100000..0x001001ff [0x200 / 1 blocks]. OK
0x00100200..0x00100e7f [0xc80 / 7 blocks]..... OK

Resetting hardware...
All done.

Have a nice day!
```

b) 刷到这里的时候,会停在下面的图上,因为端口号发生了变化,这个时候拔掉设备,按住设备右侧的按键不要松开,重新插上设备,在设备管理器看到端口变了,这里 是由 10 变成了 78

正在刷新 fullimage.elf.请等候片刻……

Loading ELF file 'firmware_win\fullimage-iceman.elf'...

Loading usable ELF segments:

3: U 0x00102000 P 0x00102000 (0x00031258->0x00031258> [R X] 00x94

L: U 0x00200000 P 0x00133258 (0x00001af4->0x00001af4> [RW] 00x312ec

Note: Extending previous segment from 0x31258 to 0x32d4c bytes

Vaiting for Proxmark to appear on com10......

P 电池 □ 環 端口 (COM 和 LPT) □ Proxmark3 (COM78) □ □ 计算机

c) 关掉软件,重新打开输入新的端口号

请先关闭正在运行的GUI中文或英文软件如果依然连接不上,缓慢走省略号表示串口调用冲突,需要在任务管理器中关闭"proxmark3.exe"进程。并重启刷机程序刷机过程中如果长时间等待超过一分钟无反应,不要关闭窗口,按任按钮不放,重新拔插USB口即可强制刷入,直至升级完成即可松开按钮!

请输入【设备管理器一端口一Proxmark3】的串口号<例如"5"):78

正在刷新 fullimage.elf.请等候片刻…… Loading ELF file 'firmware_win\fullimage-iceman.elf'... Loading usable ELF segments: 0: U 0x00102000 P 0x00102000 <0x00031258->0x00031258> [R X] 00x94 1: U 0x00200000 P 0x00133258 <0x00001af4->0x00001af4> [RW] 0x312ec Note: Extending previous segment from 0x31258 to 0x32d4c bytes Waiting for Proxmark to appear on com78. Found. Flashing... Writing segments for file: firmware_win\fullimage-iceman.elf 0x00102000..0x00134d4b [0x32d4c / 407 blocks]...

恭喜您! iceman固件全部刷写完成! 日行一善,善如春园之草,不见其长,日有所增;日行一恶,恶如磨刀之石,不见其亏,日有所减! BinAry

青按任意键继续....