

RAINFALL AT Llangammarch Wells

Lat. _____

Long. _____ County of Brecon _____

Wye - 8.

Rain Gauge, by _____

Observer W Black Jones M.D.

Diameter	8										
Height	1 - 0										
Altitude	551 T										
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January	28.90						(1.90) 2.19	3.26	9.61		
February	18.30						(1.15) 3.91	3.01	6.05		
March	20.70						(6.90) 7.97	1.75	2.22		
April	9.50						(1.15) 4.73	2.81	5.03		
May	13.20						(2.20) 1.41	3.64	3.37		
June	14.80						(2.05) 2.69	2.65	1.91		
July	21.00						2.45 2.68	.98	1.16		
August	27.80						2.78 5.74	4.56	1.78		
September	13.80						8.15 4.61	1.29	2.94		
October	33.50						5.39 2.04	6.55	5.11		
November	31.80						1.34 4.28	3.70	3.93		
December	29.00						7.79 7.53	6.48	3.67		
TOTALS	(262.30)						(41.25) 49.78	40.68	46.78		

*

†

Llangammarch Church $\frac{3}{4}$ mile W.

Trees 30 ft high 150 ft N.W.

† 1896 Jan - June est² from Benthall

* 1890-95 computed from Llanwrtyd Wells & Aberystwyth

RAINFALL AT Llangammarch Wells

Lat.

Long.

County of

Brecknock

Glasbacher

Rain Gauge, by

Observer Dr W Black Jones

Wye-8.

Diameter ..	8										
Height	10										
Altitude ..	551										
Year ..	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	6.00	4.50	3.03	8.34	6.61	2.46	8.07	3.06	3.19	3.39	4.865
February ..	5.17	2.00	1.49	5.32	6.02	2.64	4.76	3.26	3.09	.93	3.468
March ..	1.44	5.25	3.50	10.30	2.89	7.71	4.41	2.09	4.85	4.48	4.692
April ..	2.40	3.92	2.31	2.06	2.71	5.47	1.46	2.83	2.99	4.37	3.052
May ..	3.86	.99	3.09	4.16	2.49	.52	3.51	3.61	3.19	2.20	2.764
June ..	3.73	2.39	2.59	2.56	2.02	2.53	3.15	5.59	1.32	2.87	2.875
July ..	2.73	2.17	2.23	3.12	2.33	1.56	1.37	5.71	5.34	4.32	3.088
August ..	4.49	3.61	3.95	7.77	3.64	5.74	4.32	3.89	5.94	1.77	4.512
September ..	2.80	2.90	2.10	5.49	2.54	3.16	1.67	.75	3.47	3.75	2.863
October ..	7.91	3.65	4.46	11.67	3.13	2.93	7.53	7.56	2.48	8.32	5.964
November ..	3.99	2.79	4.20	3.70	3.52	4.89	5.18	4.05	3.89	2.73	3.914
December ..	8.38	8.84	5.03	4.76	4.50	1.73	4.83	6.52	4.67	8.83	5.809
TOTALS ..	52.90	43.01	37.98	69.45	42.40	41.34	50.26	48.92	44.42	47.96	4.864

✓

1900 Llangammarch Church 1 mile SW

1903 Station 1 SW

Gauge in a field a considerable distance from any trees

HWB

+ Inspected H.R.M. 1904. Glasbacher g. in ground of Lake Hotel.

RAINFALL at Llangammarch Wells

County of Brecon

Observer Dr W Black-Jones

River Basin Wye 8

Snowdon Rain Gauge, by

Diameter ...	8										
Height	1.0										
Altitude ...	551 ft										
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	5.98	20.8	6.22	7.71	4.54	6.31					
February ...	6.95	4.29	3.29	2.84	7.66	8.30					
March	1.89	2.49	9.48	8.85	7.54	1.67					
April	3.50	3.18	.71	7.45	1.90	1.84					
May	2.40	2.93	1.19	3.25	2.54	3.67					
June	5.60	3.31	5.06	3.15	1.91	1.89					
July	4.39	.62	6.14	1.06	4.66	8.33					
August	6.16	4.52	9.57	2.30	4.24	4.03					
September ..	.50	3.35	1.12	3.61	2.39	1.15					
October ...	4.28	5.74	5.71	5.47	2.85	3.48					
November ..	7.63	7.01	5.03	6.73	6.39	4.70					
December ...	9.52	11.13	7.79	3.61	11.96	10.27					
TOTALS ...	58.80	50.65	59.31	56.03	58.62	55.59	NR.				
	2	2	2	2	2	2					

1913 f in open field

+ Inspected

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
1911			Llangammarch	1 mi	SW	Llangammarch	1 mi	SW