

## RAINFALL at Swinderby Ling Moor

County of Lincolnshire

Observer Cecil H Wraying

River Basin Trent. Right Bank Tributaries 6

Rain Gauge, by

Diameter ...			5								
Height .....			0.9								1.0
Altitude ...			.	50 ?							
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...			2.99	2.25	1.37	2.67	1.10	2.67	1.73	1.80	
February ...			1.31	1.07	1.06	2.81	4.16	.73	1.66	2.69	
March .....			2.45	2.76	2.24	1.16	3.93	1.61	1.32	3.13	
April .....			.26	2.09	.96	.80	2.07	1.64	1.80	2.15	
May .....			2.94	2.20	1.82	2.28	2.09	2.23	1.95	1.23	
June .....			3.98	.66	2.53	2.83	1.65	1.52	.94	1.01	
July .....			4.05	.60	3.00	5.33	1.87	1.45	2.54	2.67	
August .....			5.33	1.25	1.40	2.94	4.41	5.97	1.84	3.07	
September ..			1.03	1.60	1.50	.75	1.68	1.33	3.28	2.46	
October ...			2.17	4.14	2.16	1.23	1.82	2.74	1.77	2.27	
November ..			2.38	2.58	1.98	2.38	3.03	1.23	2.20	2.39	
December ...			2.75	.60	4.55	5.16	2.17	1.01	3.18	3.60	
TOTALS ...			31.64	21.80	24.57	30.34	29.98	24.15	24.21	28.47	

1912 Roses 1 ft high 1 ft E

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
			Swinderby	1 mi	NW	Swinderby	1 mi	NW

## RAINFALL at Swinderby Ling Moor

County of Lincolnshire Observer Capt Cecil H. May

River Basin Trent-Rt-Bank Tribes b.

(1925) N.O. Rain Gauge, by \_\_\_\_\_

Diameter ...	5"										
Height .....	0.9	1.0									
Altitude ...	50										
Year .....	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	MEANS.
January ...	2.01	2.02	2.41		2.26	1.76	2.62		4.34	2.03	2.99
February ...	1.94	29	3.20		1.73	2.05	1.54		1.64	.64	.68
March .....	2.79	1.15	1.96		1.32	1.00	1.83		2.22	.28	2.52
April .....	4.64	1.84	2.66		1.87	1.81	2.35		1.84	1.36	2.90
May .....	1.14	2.07	91		2.74	4.31	2.52		1.98	1.20	1.46
June .....	2.30	1.53	91		1.88	1.37	3.32		2.44	1.89	1.56
July .....	2.90	55	4.62		1.84	1.82	1.66		1.13	1.15	4.14
August .....	1.01	4.13	4.03		3.07	2.29	2.44		2.63	2.29	2.52
September...	1.87	96	2.56		2.72	2.92	1.35		1.41	1.48	4.27
October.....	1.18	2.35	1.45		5.05	2.44	2.17		4.40	2.98	2.50
November...	1.12	1.60	1.24		1.58	2.28	2.88		2.90	4.86	3.25
December...	2.45	2.16	3.37		2.44	1.43	1.85		2.35	4.07	2.15
TOTALS...	25.35	20.15	29.32	N.R.	27.52	23.48	24.53	N.O.	24.24	23.23	30.94
	D	D	D		D	D	D		D	D	O

1921. Bone Edging 4" high 1ft E

Position of Station on reduced Ordnance Survey } No. of Map \_\_\_\_\_ Reference No. \_\_\_\_\_

Date.	Lat. N.	Long.	Railway Station.	Distance from gauge	Direction	Parish Church.	Distance from gauge	Direction
1920			Swinderby	1 mi NW	1971 S W	Swinderby	1 mi	S W

## RAINFALL at Swindon (Long Mead)

County of Lincolnshire

Observer C.H. Wray, Esq.

River Basin Tiers - Right Bank tributary

Type of Gauge

Annual Average..... in. based on..... years obs. un-weighted. Period of average.....

Ref.

830732/26

Diameter	5										Means
Height	1	0									
Altitude		50									
Year	1931	1932	1933	1934	1935	1936	1937	1938	1939	1940	
January	3.10	1.01									
February	3.25	.91									
March	3.9	1.47									
April	3.33	2.62									
May	2.79	5.16									
June	5.05	.73									
July	4.12	5.64									
August	4.80	1.99									
September	4.14	1.75									
October	.85	3.53									
November	2.73	1.92									
December	1.55	1.08									
TOTALS	36.10	27.71	#								

Large semi-6 vane, for test and found to be falling to pieces.  
 No further observations made until 9A 1954 on file.  
 1932 info lost.

Position of Station on reduced Ordnance Survey Map, } No. of Map..... Reference No.....  
 1 mile to 1 inch Series }

Date.	Lat. N.	Long.	Railway Station.	Distance from gauge	Direction from gauge	Parish Church.	Distance from gauge	Direction from gauge