

RAINFALL AT Harrogate Skipton Road The Stray

Lat.

Long.

County of

York W.R.

Rain Gauge, by

Observer

Mr Gledhill

Ouse Nidd 11

Diameter	5										
Height	10										
Altitude									380		
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January	3.88	1.13	1.82	1.06	3.31	3.88	.78	1.77	1.45	3.35	
February	1.17	.05	2.69	3.19	5.41	.36	.70	2.72	1.78	1.46	
March	2.02	1.48	1.47	.61	2.65	2.33	3.21	3.14	1.04	1.14	
April83	2.32	1.54	.86	2.43	2.12	1.22	1.82	2.96	1.89	
May	2.17	2.20	3.37	2.38	1.92	.46	.53	1.10	2.50	3.72	
June	1.84	1.32	4.32	1.31	3.71	2.95	4.04	3.82	1.95	1.53	
July	2.36	3.64	1.51	3.19	2.68	6.94	1.65	.62	1.83	2.11	
August	4.60	3.68	3.05	2.88	2.73	3.64	1.76	3.24	3.39	1.16	
September	2.71	2.06	1.42	1.70	1.24	1.06	3.72	2.95	.88	3.35	
October87	4.06	6.72	2.12	4.40	4.64	3.51	1.81	4.37	3.01	
November	3.05	3.15	1.76	2.21	1.50	4.14	1.55	1.80	2.45	1.30	
December85	4.58	.71	3.56	2.17	3.31	4.21	2.95	2.83	3.03	
TOTALS	26.35	30.08	30.38	25.07	34.15	35.83	26.88	27.74	27.43	27.05	

1891 Rain Gauge moved to The Stray - Previous position unknown

RAINFALL AT Hannogate The Stray

Lat.

Lon.

County of York W.R. Northern

Rain Gauge, by

Observer Mr. Gladhouse

Wind - II.

Diameter ..	5										
Height ..	1	0									
Altitude ..	380										
Year ..	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	3.73	1.40	1.34	2.03	2.65	.99	3.76	1.37	1.22	1.25	1974
February ..	5.65	1.26	1.34	2.50	3.52	1.61	2.07	2.12	1.75	.80	2362
March ..	.84	2.02	1.23	3.61	2.15	2.81	1.90	2.08	3.42	3.89	2395
April ..	1.70	2.32	1.63	1.39	1.61	2.55	.80	1.36	2.81	2.97	1914
May ..	1.49	.90	2.43	4.57	3.28	.67	2.50	4.42	2.80	1.81	2487
June ..	3.59	1.42	2.29	2.78	1.71	1.15	1.38	3.20	1.26	3.68	2246
July ..	3.21	1.26	1.80	3.35	.83	1.39	1.72	1.69	2.71	3.16	2112
August ..	4.44	1.64	2.52	2.84	2.32	3.80	2.76	1.81	1.60	3.39	2712
September ..	.42	1.01	1.04	4.03	1.13	1.83	.55	1.01	1.73	1.80	1455
October ..	3.36	1.73	3.46	7.70	.64	1.80	4.00	7.25	1.41	2.36	3371
November ..	3.39	4.31	1.95	1.62	2.81	3.88	3.50	2.93	1.55	.90	2684
December ..	3.01	3.66	1.83	1.55	1.47	.58	2.22	3.19	1.23	4.11	2283
TOTALS ..	34.83	22.93	22.86	37.97	24.12	23.04	27.16	32.43	23.49	30.12	27.85

M D S D S D S

Hub

RAINFALL at Harrogate The Strand

County of W Yorkshire

Observer Mr G.W. Gledhill

River Basin One-Nidd 11

Sunderon Rain Gauge, by

RAINFALL at Harrogate The StrayCounty of W. R. YorkshireObserver Mr G. W. GledhillRiver Basin Ure - Nidd 11Snowdon Rain Gauge, by

Diameter ...	5"										
Height	1 0										
Altitude ...	380										
Year	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	MEANS.
January ...	3.67	4.43									
February ...	2.60	1.12									
March	2.75	1.86									
April.....	4.58	1.56									
May	1.62	2.02									
June	1.88	2.3									
July	6.27	1.83									
August	1.54	2.52									
September...	1.87	1.99									
October.....	3.07	1.73									
November...	2.03	2.50									
December...	4.02	4.07									
TOTALS...	34.80	24.16									

Position of Station on reduced Ordnance Survey Map, 2 miles to 1 inch Series } No. of Map _____ Reference No. _____

Date.	Lat. N.	Long.	Railway Station.	Distance from gauge	Direction from gauge	Parish Church.	Distance from gauge	Direction from gauge