

## RAINFALL AT

Heaton Moor W.W.

Lat.

Lon.

County of

Cumberland

Rain Gauge, by

Observer

F. J. Edge Esq. C.B.  
R. Robertson Esq.

West Coast Streams - 3.

Diameter .....					5						
Height .....					1 3						
Altitude .....						395 T					
Year .....	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January .....					5.74		10.00	1.17	9.38	9.84	
February .....					5.64		4.86	4.90	4.80	5.19	
March .....					1.88		6.42	9.10	1.88	4.91	
April .....					2.39		1.56	4.00	6.04	6.93	
May .....					4.14		1.78	3.70	2.90	4.13	
June .....					4.48		7.24	6.30	1.87	1.77	
July .....					3.58		10.75	2.60	.81	4.71	
August .....					5.99		11.04	8.50	11.82	2.40	
September....					.45		14.07	6.30	5.03	4.70	
October.....					6.29		20.21	5.00	5.16	2.97	
November....					9.97		7.60	10.10	7.59	10.02	
December....					10.70		19.43	11.20	8.78	4.22	
TOTALS .....					61.25		114.96	72.87	66.06	61.81	

1894 Heaton Moor 2 miles W

RAINFALL AT Cleator Moor Water Works

Lat.

Lon.

County of Cumberland

Rain Gauge, by

Observer R. Robertson Eng Cl

W. Coast streams - 3.

Diameter ..	5										
Height ....	1.3					1.6		0.6			
Altitude ..	395 T										
Year ....	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	6.63	2.77		6.76	7.04	2.28	5.98	1.64	6.70	3.41	
February ..	5.08	2.50		5.26	4.07	2.72	3.76	2.06	2.16	3.11	
March ..	.57	2.25		8.77	5.71	6.41	2.54	5.29	3.61	4.56	
April ..	3.03	5.12		1.94	4.53	4.90	2.26	5.23	2.21	4.68	
May ..	4.27	2.42		3.11	3.08	5.56	8.32	5.65	3.71	3.34	
June ..	3.85	3.84		3.50	2.00	3.26	2.34	8.51	3.57	4.10	
July ..	2.90	.95		7.59	3.71	3.01	3.15	2.59	5.24	8.64	
August ..	8.69	6.81		6.19	6.22	4.53	6.81	6.43	5.47	4.32	
September ..	5.33	3.73		8.36	5.24	3.57	1.60	1.98	7.91	2.40	
October ..	5.68	9.12		13.20	4.81	4.10	7.63	9.79	2.23	18.15	
November ..	6.45	6.34		5.24	3.75	5.96	5.05	6.46	5.26	3.08	
December ..	9.66	5.43		4.56	6.73	6.48	3.40	10.06	5.47	11.10	
TOTALS ..	62.14	51.28	No Reply	74.48	56.89	52.78	52.84	65.69	53.54	70.89	

1908 Cleator Burnch 1 1/4 miles W

Station

Gauge on grass land.

## RAINFALL at Cleator Moor Water Works, Dent Reservoir

County of Cumberland Observer R. Robertson C.E.

River Basin West Coast Streams 3

Rain Gauge, by Stanley &amp; Sons

Diameter ...	5										
Height .....	0.6		1.0								
Altitude ...	395 T	M									
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	8.35	2.92	5.32	4.54	4.04	6.03	5.62				
February ...	8.33	7.02	3.21	2.60	7.06	8.78	4.35				
March .....	1.69	1.55	6.70	5.30	6.29	2.51	.81				
April .....	3.24	5.05	1.12	4.07	1.85	3.82	3.67				
May .....	2.72	5.06	2.58	5.47	2.65	1.42	3.19				
June .....	1.84	4.47	7.12	3.26	1.16	1.50	4.61				
July .....	5.49	1.29	3.09	.97	5.56	8.81	3.86				
August .....	9.26	3.39	6.58	3.03	5.42	2.01	3.59				
September ..	.83	4.02	2.24	3.17	2.20	2.05	3.38				
October ...	2.11	4.09	6.40	5.20	1.96	2.15	9.30				
November ...	6.48	7.10	5.92	5.68	7.02	1.93	8.22				
December ...	7.27	14.09	7.09	3.74	9.13	8.79	6.79				
TOTALS ...	62.61	60.05	57.37	47.03	54.34	49.80	57.39	N.O.	N.R.		

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
1911			Cleator Moor Brimington	1½ mi	NW	Cleator	1½ mi	SW