

RAINFALL AT Snowdon N° 13 Glaelyn

Lat.

Lon.

County of

Carnarvon

Rain Gauge, by

Observer

J. R. Gethin Jones Esq

Glaelyn - 5.



Diameter										
Height										
Altitude										
Year /.....	1890	1891	1892	1893	1894	1895	1896	1897	1898	MEAN.
January										
February										76.43
March										
April										24.75
May										
June										30.30
July										
August										
September										12.55
October										{ 16 Nov 9 32.40
November										} 1 Nov 9 - Dec 10
December										20.50
TOTALS										

Dec 10th 1898 - March 76.43

Aug & Sept measured 04.68 20.40

Oct 6th March 23 1900 gauge overflown

1898 from Mr. Gethin Jones's original letters. Int. 25 x 1.08



RAINFALL AT

Glaslyn

No 13

Lat.

Lon.

County of

CAERNARVONSHIRE

Rain Gauge, by

Observer

J. R. Gehring Jones Esq

Glaslyn - 5.

Diameter ..	5										
Height ..	10										
Altitude ..	2500										
Year ..	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..											31.10
February ..											19.00
March ..											216.90
April ..		58.40									
May ..	53.60						80.20				
June ..											25.40
July ..											
August ..								159 103.60	"		35.50
September ..				43.90							
October ..	125.50	128.30									27.40
November ..											
December ..								59.80 31.50	73.00	50.00	
TOTALS ..		186.70					179.50	176.60	205.30		

1899 Oct 6th to Feb 1900 Gauge filled with water by snowbank

1902 Observations interrupted by illness

1904 Dec 31 Estimated from Dec 20-31 according to elevation at Pen-y-pas for same period