

## RAINFALL AT Castlewellan Corbett Reservoir

70

Lat.

Lon.

County of Down

Rain Gauge, by

Observer

J. Smyth Jun?

Barrn, upper - 7.

Diameter . . .										100	
Height . . .										3 ..	
Altitude . . .										234-	
Year . . .	1870	1871	1872	1873	1874	1875	1876	1877	1878	1879	MEANS,
January . . .										5.70	2.60 1.70
February . . .										1.70	2.10 .90
March . . .										2.40	.70 1.60
April . . .										3.60	1.50 1.40
May . . .										3.70	4.50 4.20
June . . .										2.20	2.80 5.60
July . . .										4.20	.30 6.10
August . . .										2.80	3.40 4.90
September . . .										1.90	3.90 4.90
October . . .										3.20	2.80 1.20
November . . .										3.50	1.30 2.20
December . . .										2.60	.30 1.20
TOTALS . . .										37.50	26.20 35.90

RAINFALL AT Banbridge Corbet Reservoir

Lat.

Lon.

County of Down

Rain Gauge, by

Observer

J. Smyth, jun., Esq., C.E.

Benn. Upper - 7.

Diameter ....	<input checked="" type="checkbox"/> 10										
Height .....	3.0										
Altitude ....	2347										
Year .....	1880	1881	1882	1883	1884	1885	1886	1887	1888	1889	MEANS.
January .....	.70	.10	2.0	5.10	3.40	2.10	2.20	2.30	1.60	1.90	2.150
February ....	2.50	1.60	3.10	2.40	3.30	3.50	1.90	1.50	.20	.80	2.080
March .....	1.90	2.30	2.50	.70	2.70	2.10	2.50	1.10	2.50	1.50	1.980
April .....	4.50	1.60	3.50	1.40	2.10	2.70	1.60	1.80	1.80	3.30	2.480
May .....	.60	2.20	2.60	2.50	3.30	2.30	4.80	1.40	2.40	2.60	2.470
June .....	3.40	4.20	3.80	1.80	1.40	4.40	1.40	.50	3.30	.10	2.030
July .....	5.20	2.90	3.90	4.10	3.70	1.80	4.10	2.50	5.50	3.80	3.750
August .....	.80	5.10	5.00	3.50	1.60	1.70	2.60	2.00	2.50	6.40	3.120
September ...	3.40	1.40	4.50	5.80	1.40	6.40	2.30	1.40	.70	1.30	2.860
October ....	1.60	3.00	3.70	2.70	2.10	2.80	5.00	1.30	1.65	3.70	2.755
November....	2.80	5.00	5.20	3.00	2.90	2.40	3.40	1.80	4.60	.60	3.170
December ...	1.80	2.00	3.10	1.60	2.30	1.60	3.70	1.30	2.60	2.20	2.220
TOTALS .....	29.20	31.40	45.00	34.60	30.20	29.80	35.50	18.90	29.35	28.20	31.015

1888 Feby amount rather small; gauge believed to be insufficiently delicate to measure accurately the small quantities which fell.

## RAINFALL AT Banbridge Corbet Reservoir

Lat.

Lon.

County of

Down

Rain Gauge, by

Observer

Barn Upper - 7.

Smyth Eng. Co.

Diameter	10	10	5								
Height	3 0		1 0								
Altitude	234 T										
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January	2.20	.76	.65		2.60	1.75	1.40	2.20	1.15	2.73	
February	.80	.00	.20		2.35	.30	1.40	1.25	1.65	3.00	
March	1.50	.27	.50		.80	1.95	2.65	4.35	.65	1.40	
April	.70	1.85	.17		2.10	1.40	.90	2.35	2.55	2.68	
May	1.10	1.15	1.54		1.65	.15	.25	.90	3.35	3.20	
June	2.10	2.40	.83		2.25	1.60	3.06	4.90	2.70	4.00	
July	1.50	1.57	.75		3.10	4.60	5.85	1.60	.40	2.05	
August	2.30	4.22	2.70		1.95	5.30	1.68	3.60	3.00	1.50	
September	2.70	1.55	.95		.15	.45	4.60	1.55	3.65	3.10	
October	1.40	3.60	1.40		4.65	3.30	1.65	1.40	3.00	1.75	
November	5.65	2.65	1.20		3.40	2.75	.85	2.80	1.80	1.90	
December	1.10	3.00	.40		1.90	3.15	3.45	2.95	1.93	3.60	
TOTALS	23.05	?			26.90	26.70	27.74	29.85	25.83	30.91	
	28.02	11.29									

1891 Much too small 1892 ditto. gauge leaking  
 Copper Snowdon fixed 1-1-93.

## RAINFALL AT Barbridge Corbet Reservoir

Lat. ....

Lon. ....

County of Down

Rain Gauge, by .....

Observer J. Smyth Esq. C.E.

Bann, Upper - 7.

Diameter ..	10	□	5								
Height ....	3	0	1	0							
Altitude ..	234										
Year ....	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	1.55	2.80	2.20	3.65	2.75	1.55	2.44	.82	1.90	1.55	2.121
February ..	1.85	1.35	2.05	1.75	3.05	1.03	1.94	1.26	1.33	1.26	1.687
March ....	.70	1.80	1.47	4.82	1.58	8.05	1.28	2.40	3.73	2.23	2.306
April.....	1.65	2.00	2.34	1.07	1.27	2.03	1.80	2.65	2.13	2.83	1.977
May .....	2.15	1.70	3.95	2.08	2.15	1.02	3.09	2.91	2.00	1.14	2.219
June.....	2.67	1.90	2.60	1.20	1.65	2.30	.90	4.00	1.92	1.85	2.099
July .....	3.48	1.09	3.40	5.10	2.37	1.09	1.57	1.94	2.80	3.53	2.637
August ....	4.83	4.10	2.29	4.16	4.70	5.70	3.15	2.38	2.30	2.00	3.561
September..	1.45	2.89	3.50	3.40	2.15	1.08	.50	1.05	4.03	2.25	2.230
October....	4.05	2.47	1.50	4.32	.73	.98	5.13	4.50	2.33	4.75	3.076
November..	4.55	3.65	3.54	1.63	1.87	2.84	1.97	2.47	2.13	.85	2.550
December ..	3.38	2.70	2.18	2.35	1.77	1.59	2.55	1.70	2.78	2.78	2.378
TOTALS ..	32.31	28.45	31.02	35.53	26.04	24.26	26.32	28.08	29.38	27.02	28.841

→ → → → → → → → → →

1909. Corbet Station

2 miles NW.

Hull

RAINFALL at Banbridge Corbet Reservoir

County of Down

Observer John H. E. D. Evans

River Basin River Upper

Rain Gauge, by

Diameter ...	5										
Height .....	10				9						
Altitude ...	284										
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	1.55	.68	3.16	3.58	90		1.73	1.87			
February ...	3.51	2.37	3.08	.86	3.16		2.39	2.03			
March .....	1.33	1.05	2.89	2.33	3.00		1.38	2.18			
April .....	2.18	2.33	1.27	2.14	1.31		3.16	1.87			
May .....	1.33	1.40	.82	0.09	1.30		5.03	3.77			
June .....	3.60	2.22	4.80	3.00	1.04		2.33	1.9			
July .....	3.70	2.10	3.55	1.78	1.78		2.75	2.59			
August .....	3.80	1.26	5.60	.59	2.46		2.89	3.41			
September ..	1.14	1.10	.45	5.10	1.15		.95	1.87			
October ...	1.50	3.35	1.70	0.10	98		6.40	3.65			
November ...	2.50	3.24	2.23	2.84	3.75		3.42	3.05			
December ...	4.21	4.25	3.34	2.64	6.13		2.02	1.75			
TOTALS ...	30.35	25.35	32.89	30.65	26.96	N.R.	34.41	31.53			

+ D D

Obsns at noon.

Date.	Lat. N.	Long. W.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
1912	54.19.10	6.1	Corbet	2 mls.	NW.			