

RAINFALL AT Stanedge Castleshaw Cudworth

Lat.

Lon.

County of York W.R. Central

flaicher Rain Gauge, by Caselli  
Mersey Sondor Upper H. Observer C. J. Bailey Esq. CL

Diameter ..	5										
Height ..	4.6										
Altitude ..	1410 T										
Year ..	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	2.34	1.27	2.45	1.97	.81	3.41	.93	1.64	1.31		
February ..	1.25	1.35	1.52	2.60	.73	1.91	1.00	1.75	.84		
March ..	1.61	1.13	3.21	2.34	2.30	1.79	1.78	2.33	3.25		
April ..	1.95	2.25	1.65	1.32	2.74	1.60	2.23	2.36	2.71		
May ..	1.88	3.25	4.88	3.77	.61	3.58	3.65	2.81	2.28		
June ..	1.19	1.88	2.14	1.03	2.87	1.92	4.56	2.40	3.57		
July ..	4.15	2.44	3.39	1.55	2.05	1.58	2.50	4.46	5.08		
August ..	1.75	4.80	3.98	4.56	4.91	2.80	2.64	3.67	3.33		
September ..	.84	3.11	5.51	1.25	2.56	.78	.73	3.13	2.72		
October ..	2.33	5.23	7.30	.95	2.23	6.86	7.89	2.74	3.33		
November ..	5.32	2.41	2.06	1.65	4.84	3.62	2.59	1.24	.65		
December ..	2.59	1.97	1.57	2.04	.89	2.22	2.30	1.99	5.16		
TOTALS ..	27.20	31.09	39.66	25.03	27.54	32.07	32.80?	30.52?	34.23		

1901 Deep Church  $\frac{1}{2}$  miles S

Wall 3 ft high  $\frac{3}{4}$  yard S E

Deep Station 3 miles S

Hills soft high 900 ft N

1907 ? small

1908 "

+ Inspected

Reports from survey 1910.

## RAINFALL at Standedge Castlehead Cudworth

County of W.R. Yorkshire

Observer C.J. Ballingby C.B.

River Basin Upper Mersey 4

Smooror Rain Gauge, by Casarotti

Diameter ...	5										
Height .....	4 6										
Altitude ...	1410 ft										
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ....	2.96	.77	3.59	3.05	2.20	3.40	1.31	2.45	2.44	3.49	
February ...	1.80	1.48	2.16	.69	1.33	2.21	3.77	1.18	3.10	1.65	
March .....	.49	2.04	3.54	2.91	2.86	1.63	4.76	2.42	1.63	3.82	
April .....	2.91	1.64	.40	2.97	.95	1.00	1.74	1.51	1.83	1.76	
May .....	2.84	1.03	5.54	2.22	1.84	2.56	3.51	3.28	2.85	1.65	
June.....	4.72	2.82	4.08	1.50	4.02	1.29	3.38	2.55	.99	1.47	
July .....	3.53	.54	6.05	1.58	4.14	5.24	1.81	1.31	4.19	2.97	
August.....	4.14	2.69	7.23	2.14	2.14	6.88	2.61	5.95	2.79	5.51	
September ..	.18	3.45	1.69	2.40	1.84	.82	2.37	1.12	12.21	1.86	
October ...	3.16	3.55	3.77	3.75	3.37	2.52	3.98	4.50	1.92	4.86	
November ..	3.36	3.33	1.60	2.50	3.51	2.21	2.58	1.83	1.45	2.74	
December ...	3.77	3.61	3.02	1.37	5.38	6.98	2.54	2.05	4.75	2.80	
TOTALS ...	33.86	26.95	42.67	27.08	33.62	36.74	34.36	30.15	40.05	32.08	

1912 Well 100 ft high 30 yds N

+ Inspected

Rejected from Survey, 1912.

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
			Deepl	2½ m	SE	Deepl	2½ m	SE

## RAINFALL at Standedge Castle Shaw Bradworth

County of W. R. Yorkshire Observer G. J. Batley Esq. C.E.

River Basin Upper Mersey 4.

Standedge Rain Gauge, by Casarilli

Diameter ...	5"										
Height .....	4 6										
Altitude ...	1410										
Year .....	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	MEANS.
January ...	2.52	4.00	3.02	1.92							
February ...	2.04	3.0	2.78	4.07							
March .....	2.02	1.66	2.45	2.15							
April .....	6.01	1.92	3.68	2.77							
May .....	4.81	2.19	1.59	3.75							
June .....	3.28	4.3	2.15	.88							
July .....	9.01	1.20	5.16	4.49							
August .....	2.09	6.00	7.51	3.80							
September...	1.89	1.28	3.11	2.53							
October....	2.26	2.34	1.60	2.96							
November...	1.53	2.60	1.99	3.27							
December...	3.09	3.26	2.72	3.00							
TOTALS...	40.55	27.15	37.76	35.49	#						

1920 Hills 1000 ft high 300 yds N

Rejected from survey 19" low.

Position of Station on reduced Ordnance Survey Map, 2 miles to 1 inch Series			No. of Map	Reference No.				
Date.	Lat. N.	Long.	Railway Station.	Distance from gauge	Direction from gauge	Parish Church.	Distance from gauge	Direction from gauge
1920			Delph	2½ mi	SE	Delph	2½ mi	S
1922	53°35' 41" S	1°59' 33" E						