

RAINFALL AT Fawcett, Spinkaburn

Lat.

Lon.

County of York N. R.

Rain Gauge, by

Observer

J. Hewson, Eng., C.E.

Ouse-Wharfe - 10

Diameter							8			
Height							6		9	
Altitude							620T			
Year.....	1880	1881	1882	1883	1884	1885	1886	1887	1888	MEANS.
January							6.07	2.58	1.15	.99
February							1.34	.92	.85	1.65
March							3.45	1.33	4.81	2.13
April							2.38	.79	3.44	3.34
May							4.66	1.92	.98	2.60
June							1.27	.11	3.12	.20
July							3.03	1.43	5.93	1.90
August							2.05	2.56	3.68	4.62
September....							2.16	4.20	.62	1.39
October							4.48	2.47	.79	5.22
November....							2.40	3.08	6.67	1.04
December ...							4.23	2.28	2.22	1.72
TOTALS							37.52	23.67	34.26	26.80

RAINFALL AT Fewston Springsburn

Lat.

Lon.

County of

York W.R.

Rain Gauge, by

Observer

J. Fewston Esq. C.R.Ouse - Wharfe 10

Diameter	8										
Height	0 9										
Altitude	620 T	636 T									
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January	3.72	1.79	2.48	1.24	4.02	4.66	1.36	2.36	2.37	4.80	2.880
February	1.00	.18	3.93	4.31	5.75	.61	.89	3.12	2.65	1.73	2.417
March	2.45	2.02	1.50	.58	2.82	2.51	3.79	4.14	1.48	1.42	2.301
April	1.54	2.37	1.89	.79	2.31	2.07	1.86	2.26	2.49	2.79	2.027
May	2.73	1.82	3.19	2.11	1.61	.55	.48	1.13	2.46	3.20	1.928
June	3.35	1.01	4.30	2.16	3.11	2.48	5.07	3.93	2.03	1.63	2.907
July	2.01	4.13	1.54	3.00	3.47	4.81	1.92	1.56	2.21	2.06	2.671
August	4.66	4.04	4.12	2.88	2.95	2.41	1.89	4.02	3.70	1.62	3.229
September	2.19	1.92	1.71	1.90	.75	1.83	4.03	3.12	.79	3.77	2.221
October	1.42	3.94	6.63	2.82	4.72	4.51	3.49	1.67	5.04	2.84	3.708
November	3.39	3.12	2.03	2.17	1.62	3.80	1.64	2.27	2.81	1.23	2.408
December	1.05	4.63	1.10	3.36	2.68	4.07	4.30	2.99	3.59	3.84	2.161
TOTALS	29.51	30.97	34.42	27.62	35.81	34.31	31.02	32.57	31.62	30.93	31.878

RAINFALL AT Fewston Spinksburn

Lat.

Lon.

County of York wR Northern

Rain Gauge, by

Observer T. Henderson Eng Cl.Wharfe - 10.C. G. Homzelle Eng Cl.

Diameter ..	8										
Height	0 9										
Altitude ..	6357										
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	4.48	2.27	1.86	2.81	2.86	1.40					
February ..	6.64	1.69	1.49	3.82	3.52	1.95					
March	1.15	2.26	1.38	4.53	2.16	3.01					
April	1.91	2.74	1.68	1.63	2.28	2.62					
May	1.48	1.45	2.74	3.69	2.99	.56					
June	3.12	1.65	2.57	1.74	2.00	1.54					
July	3.06	1.91	2.18	3.93	2.97						
August	5.16	1.37	4.33	5.04	3.96						
September..	.84	1.00	1.39	4.26	1.42						
October....	4.00	1.81	3.62	8.21	1.05						
November ..	3.68	4.52	2.03	2.09	3.49						
December ..	3.51	4.42	2.72	1.79	1.91						
TOTALS ..	39.03	27.09	27.99	43.54	30.60						