

RAINFALL AT *Hucknall Torkard Forge Mills*

80

Lat.

Lon.

County of *Notts*

Rain Gauge, by

Observer *J. D. Walker, Esq*

Trunk, Blank 5.

Diameter		5										
Height		1.0										
Altitude					200?							
Year	1880	1881	1882	1883	1884	1885	1886	1887	1888	1889	MEANS.	
January		.59	2.82	2.37	2.41	1.89	3.03	1.78	.61	1.25		
February		4.31	1.91	3.55	1.73	2.36	.35	.45	.78	1.20		
March		2.98	1.72	.98	1.70	1.13	2.92	1.25	2.12	3.43		
April		.92	2.85	2.58	1.82	1.48	1.70	1.08	2.39	2.73		
May		1.19	2.74	1.67	.73	1.65	5.70	1.42	.70	3.05		
June		2.20	4.47	3.93	1.13	2.81	1.08	.39	1.17	.38		
July		1.30	2.98	2.17	3.85	.44	4.10	1.39	4.80	2.80		
August		6.07	1.59	1.23	1.79	2.06	1.90	1.58	2.47	2.73		
September		1.94	1.88	5.82	.92	2.79	1.33	2.43	.80	2.40		
October		4.15	5.75	2.23	.94	5.81	4.50	1.49	.56	3.01		
November		3.18	3.44	3.48	1.15	2.65	1.53	1.46	3.10	.70		
December		3.09	4.72	1.05	2.04	.66	2.91	1.65	1.75	1.44		
TOTALS		31.92	36.87	30.87	20.21	25.72	31.05	16.37	21.25	25.12		

RAINFALL AT *Glucknall Torkard Forge Mills*

Lat. _____ Lon. _____ County of *Notto*

Rain Gauge, by _____ Observer *J.D. Walker Esq*
Front, L. bank - 5.

Diameter	5											
Height	1 0											
Altitude	200?											
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.	
January	2.52	1.59	1.13	1.65	1.79	3.53	.71	1.76	.66	2.60	1.794	
February	.68	.16	1.32	2.36	1.80	.17	.69	3.07	.97	1.43	1.265	
March	1.34	1.34	.68	.19	.78	1.48	2.24	1.85	.82	.76	1.148	
April	.46	1.80	.60	.47	1.63	1.63	.70	1.54	1.94	1.87	1.264	
May	2.17	2.05	2.53	2.54	1.61	.68	.37	1.12	1.87	3.04	1.798	
June	1.40	3.30	3.75	.98	1.80	.98	3.17	2.01	1.55	1.67	2.061	
July	2.13	2.60	1.97	2.98	2.27	3.42	1.85	.63	.94	1.76	2.055	
August	2.78	3.60	2.42	1.70	1.79	2.30	1.40	3.08	2.30	.49	2.186	
September....	1.48	.95	3.20	1.38	.60	.83	2.94	2.25	.45	2.78	1.686	
October	1.02	4.20	3.57	1.53	2.10	2.32	2.81	1.10	3.06	2.97	2.468	
November....	2.59	2.68	1.13	1.33	2.01	2.92	1.25	1.70	2.00	1.35	1.896	
December	.58	3.33	.80	2.26	1.81	2.08	3.79	2.91	1.69	2.27	2.152	
TOTALS	19.15	27.60	23.10	19.37	19.99	22.34	21.92	23.02	18.25	22.99	21.773	

RAINFALL AT Hucknall Torkard Forge Mills

Lat.

Lon.

County of Notto

Smarden Rain Gauge, by W. J. Casella

Observer J. D. Walker Esq

Inset - L-5.

Diameter ..	5										
Height	1.0		4.3								
Altitude ..	200 ?										
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..	3.54	1.32	.87	1.60	2.40	.82	3.30	.92	.95	1.00	1.672
February ..	3.26	1.31	2.10	.80	2.72	.64	2.47	1.67	1.58	.63	1.718
March	.62	1.58	1.39	3.05	1.71	2.03	1.38	1.24	2.85	2.98	1.883
April	.90	1.15	2.15	1.70	1.03	1.35	.42	1.75	2.08	1.16	1.369
May	1.18	.72	2.18	2.93	1.37	.35	1.65	2.88	2.02	1.11	1.629
June	3.02	1.61	1.60	1.41	.34	2.82	1.65	2.45	2.50	2.11	1.951
July	1.65	4.32	1.30	2.03	1.94	1.24	.33	2.10	3.45	3.16	2.152
August	5.03	1.55	3.03	5.33	2.63	3.15	1.32	2.09	3.23	2.90	3.026
September ..	.75	1.17	.97	2.83	1.46	1.59	.95	.62	1.42	2.56	1.432
October	1.84	1.67	2.37	6.15	.39	.95	5.26	4.34	.72	2.82	2.651
November ..	2.43	2.24	1.59	1.71	1.06	3.03	2.82	2.00	.84	.28	1.800
December ..	4.02	5.40	1.68	.93	1.59	.55	2.51	2.57	1.17	4.10	2.452
TOTALS ..	28.24	24.04	21.23	30.47	18.64	18.52	24.06	24.63	22.81	24.81	23.745

1902 January 1st Gauge moved 150 yards S
 Cottage 23 ft high 23 ft E
 1906 Bulwell Church 1 1/2 miles S
 Bactwood Station 1/4 NE

RAINFALL at Hucknall Tork and Forge MillsCounty of NottinghamshireObserver J. D. Walker EsqRiver Basin Irish-Well Bank Tributary 5

Rain Gauge, by _____

Diameter ...	5										
Height	4.3										
Altitude ...	200 ?										
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	2.05	.98	4.28	3.25	1.12	2.10	.68	2.63	1.69	3.62	
February ...	2.02	1.15	1.36	.74	1.08	2.98	4.44	.77	1.74	2.84	
March	.52	1.27	2.37	3.41	2.17	.63	4.08	1.63	.93	5.06	
April	1.48	.75	.23	2.38	.82	.63	1.24	1.06	1.57	1.54	
May	2.09	.87	2.40	2.16	1.87	1.68	2.47	2.04	2.22	1.28	
June	1.96	2.93	3.34	.46	2.25	1.00	2.02	2.10	.39	.84	
July	2.04	.04	4.41	.77	2.79	6.19	1.56	1.64	2.83	2.32	
August	3.14	1.85	5.35	1.31	2.16	2.88	2.21	3.87	1.76	2.13	
September ..	.58	1.56	.97	2.27	.64	.76	1.46	1.38	4.12	2.06	
October ...	1.63	1.65	3.03	4.97	2.12	1.59	1.91	3.24	1.19	2.52	
November ..	3.97	1.94	1.73	1.66	3.24	2.56	3.23	.94	1.51	1.48	
December ...	4.61	3.96	3.01	.81	5.18	5.12	2.24	1.01	3.27	3.98	
TOTALS ...	26.09	18.95	32.48	24.19	25.44	28.12	27.54	22.33	23.22	23.97	
	2	2	2					2	2	2 imp	

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
			<u>Bentwood Colliery</u>					

RAINFALL at Hucknall Forge MillsCounty of Nottinghamshire Observer Messrs J. T. Walker LtdRiver Basin Great - Sept Bank Tribs 5.

Rain Gauge, by _____

Diameter ...	5										
Height	4.3										
Altitude ...	200										
Year	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	MEANS.
January ...	2.71	1.98	2.91								
February ...	2.23	.26	2.38								
March	1.75	.76	1.80								
April	3.96	.78	2.73								
May	1.98	1.41	.71								
June	2.70	.53	.98								
July	4.31	.49	3.68								
August	.82	3.67	5.59								
September...	1.21	.99	2.00								
October	1.50	2.82	.62								
November...	.81	1.29	1.00								
December...	2.93	2.15	3.70								
TOTALS...	26.91	17.13	28.00#								

Position of Station on reduced Ordnance Survey
Map, 2 miles to 1 inch Series

No. of Map _____

Reference No. _____

Date.	Lat. N.	Long.	Railway Station.	Distance from gauge	Direction from gauge	Parish Church.	Distance from gauge	Direction from gauge