

RAINFALL AT

Lindal Berkhune Mines

Lat. _____

Lon. _____

County of

Lancashire

Rain Gauge, by _____

Observer

*Major Newton
J. Hodgson Esq*

Duddon 61

Diameter					5	5					
Height					9 0	9 0		8 0			
Altitude					215 T	215					
Year	1890	1891	1892	1893	1894	1895	1896	1897	1898	1899	MEANS.
January						2.24	3.01	1.49	3.90	5.54	
February						.54	2.40	3.22	2.98	2.96	
March						4.65	5.81	4.97	1.25	2.88	
April						2.36	1.43	2.67	3.67	4.34	
May					# 3.31	.96	.42	2.21	3.50	3.47	
June					4.07	1.73	2.62	5.95	2.90	1.32	
July					2.85	5.80	5.77	1.64	.58	3.06	
August					4.84	4.27	3.00	4.63	7.70	.93	
September...					.99	.12	7.04	4.77	1.83	5.05	
October.....					4.42	5.94	5.78	3.31	5.86	2.98	
November....					6.14	4.15	1.74	7.00	5.29	3.08	
December					4.58	4.96	5.60	6.77	4.72	3.93	
TOTALS						37.72	44.6	248.63	44.18	39.54	

Urswick Church 1 1/2 miles S.E.

Buildings 30 ft high 47 ft E.

20 " " 37 " N.

N.B. Rejected from survey as 5" too low.

RAINFALL AT *Lindal Beckune Mines*

Lat.

Lon.

County of *Lancashire*

North

Rain Gauge, by

Observer *F. A. Ainslie Esq*

Mrs. Harris Ainslie Esq

Hert 3 Duddon 1

Diameter ..	5										
Height	80				7.0						
Altitude ..	215T										
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEAN.
January ..	5.35	2.02	2.58	4.11	5.34	2.60	5.19	2.14	3.67	2.41	3.541
February ..	3.25	1.57	1.69	3.11	3.48	2.17	3.55	2.37	2.59	2.82	2.660
March	.60	3.54	2.86	3.89	3.68	3.37	3.38	4.47	3.57	3.67	3.303
April	3.12	2.59	1.93	2.23	3.44	4.34	2.09	2.72	1.96	4.43	2.885
May	2.54	1.92	2.80	3.37	2.21	1.11	6.07	4.66	4.82	2.52	3.202
June	3.70	2.10	1.31	2.74	1.72	2.68	3.26	8.36	2.62	2.06	3.055
July	2.18	1.18	4.17	4.16	3.61	1.94	3.02	2.95	4.93	6.86	3.500
August	8.31	4.52	4.52	5.87	3.92	6.01	4.52	4.51	3.97	4.18	5.033
September ..	2.96	1.71	1.70	6.13	3.24	3.32	2.26	.95	6.81	3.63	3.274
October	7.45	5.32	3.87	9.12	3.03	4.25	6.23	7.55	3.09	7.27	5.718
November ..	5.17	4.16	4.41	4.44	4.14	5.16	3.64	5.24	4.23	2.06	4.265
December ..	5.84	4.55	4.76	3.42	3.86	1.77	5.26	6.72	4.27	8.16	4.861
TOTALS ..	50.47	35.18	36.63	52.59	41.67	38.72	48.47	52.64	46.53	50.07	45.297

1904 March 21st 1000 yards N
 1905 Lindal Church 1/2 mile W
 Station 1/2 S.W.

N.B. Rejected from Survey as 5' too Low.

H.W.B.

RAINFALL at Lindal Moor MinesCounty of North LancashireObserver Wm. Harrison Arncliffe & CoRiver Basin Duddon + C 1Pennington Mining Co.Rain Gauge, by Orcheston
N° 177

Diameter ...	5										
Height	7.0										
Altitude ...	.			400?							
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	4.12	2.05	4.26	5.78	2.95	4.99	4.4)				
February ...	6.37	5.66	2.77	2.25	4.41	6.28	3.71				
March	2.37	2.15	5.51	3.86	5.20	2.50	1.25				
April	2.88	3.40	1.52	4.96	.96	2.62	3.49				
May	2.75	2.06	1.83	3.39	2.83	1.65	4.81				
June	3.71	2.78	5.26	2.76	1.40	1.05	3.65				
July	4.75	.74	3.26	1.93	6.44	5.05	3.35				
August	6.69	4.11	7.58	1.99	4.32	3.96	2.15				
September ..	1.39	4.90	3.41	2.48	4.19	1.89	4.12				
October ...	1.47	4.77	6.36	3.58	2.28	1.78	7.35				
November ..	8.40	4.61	4.51	4.77	5.66	2.33	4.70				
December ...	5.52	8.09	4.75	3.44	6.14	7.57	4.01				
TOTALS ...	50.42	45.32	51.02	41.19	46.78	41.67	47.06	NR			

N.B. Rejected from Survey as 5" too low.

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
			Lindal in Furness			St Peter's		