

RAINFALL AT *Loughrigg Silverthwaite*

Lat. Lon. County of *Westmorland*

Snowdon Rain Gauge, by *H. J.* Observer *W. J. Sharp*

Level - 2.

Diameter ..		5									
Height		1.0									
Altitude ..		292									
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..		5.68	6.22	11.27	9.32	4.54	11.90	3.78	10.98	7.78	
February ..		2.22	4.46	12.33	6.32	4.17	6.68	5.56	4.82	6.75	
March		4.92	5.42	12.32	5.31	6.49	5.65	8.47	7.19	5.66	
April		5.07	4.10	2.89	6.79	6.61	2.52	3.37	3.28	4.79	
May		1.70	3.98	4.77	4.32	2.69	8.44	7.34	5.73	3.39	
June		3.84	1.56	2.98	2.77	3.62	2.32	11.07	4.15	2.83	
July		1.42	3.89	6.57	4.11	3.00	3.83	3.16	5.73	8.61	
August		7.87	5.34	9.85	5.83	7.60	6.54	7.69	8.52	4.23	
September ..		5.15	3.78	6.88	4.74	5.19	2.70	1.57	8.64	4.68	
October		8.08	8.65	16.93	4.69	5.34	10.91	9.82	4.12	15.27	
November ..		12.16	6.91	4.85	7.12	9.55	6.97	7.80	6.57	4.60	
December ..		10.07	9.59	6.53	8.20	7.42	5.69	13.62	7.85	13.98	
TOTALS ..		68.18	63.90	98.17	69.62	66.22	74.15	83.25	77.58	82.57	

1905 Brathay Church 2 Miles E
Windermere Station 8 . S.E.

g. protected } see letters preserved -
after a time }

Rejected from Survey 5" too low

Obst., in letter dated 17. 1. 05, says value too small, as the exposure of the g.
is unfavourable.

RAINFALL AT *Longhridge Linschwaite*

Lat.

Lon.

County of *Westmorland*

Amateur make Rain Gauge, by

Observer *Miss Ashurst*

Even - 2. 2nd Gauge

Diameter ..								5			
Height								10			
Altitude ..								280			
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..						(4.61)	12.11	4.23	11.64		
February ..						4.55	6.48	6.99	5.11		
March						6.41	5.78	8.94	7.39		
April						6.95	2.33	3.00	3.27		
May						2.85	8.27	7.26	5.62		
June						3.90	2.34	10.74	4.01		
July						2.84	4.26	2.95	5.56		
August						7.31	6.90	7.55	8.38		
September ..						4.97	3.35	1.63	9.42		
October						5.41	11.71	9.67	4.24		
November ..						9.30	8.82	7.76	7.44		
December ..						7.32	6.49	14.05	7.76		
TOTALS ..						(66.42)	78.94	84.97	79.84		

1905 January partly computed

This gauge is less exposed than Daily

1906 Windermere Station 8 miles SE

1907 Brathay Church 2 miles E

Rejected from Survey : 7' too low

RAINFALL at Loughrigg Silverthwaite No 1County of WestmorlandObserver Miss A. SharpRiver Basin Laver 2Smother Rain Gauge, by N 53

Diameter ...	5											
Height	1.0											
Altitude ...	292.2											
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.	
January ...	11.41	5.32	8.80	11.75	6.52	8.04	11.55	4.12				
February ...	12.71	12.26	6.26	6.80	10.69	13.56	7.39	1.70				
March	5.48	3.71	11.13	9.72	8.64	3.00	1.64	3.92				
April	4.93	5.71	2.28	8.80	2.30	4.81	3.95	2.67				
May	3.28	3.64	3.44	4.56	3.41	1.71	4.15	4.28				
June	2.55	5.94	7.71	6.14	1.30	2.43	4.30	3.38				
July	5.39	1.31	6.32	1.02	4.80	6.36	3.24	2.17				
August	11.30	6.01	8.36	3.04	6.05	3.51	2.88	12.54				
September ..	7.2	6.05	3.35	2.86	3.81	1.80	2.87	7.38				
October ...	4.45	7.76	9.98	4.57	2.90	2.51	15.11	13.02				
November ..	7.82	13.28	7.96	9.33	14.67	4.19	11.91	8.20				
December ...	11.34	15.52	13.15	6.84	12.30	12.72	8.10	4.44				
TOTALS ...	81.37	86.51	88.74	75.43	77.42	64.14	76.99	67.82				

1911 g. on exposed bluff of rock

1912 Trees

Rejected from Survey: 5' too low

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
1911			Windermere Coniston	8 mi 6 mi	SE SSW	Prathay	2 mi	E